

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22011594/TPA3Q2
Date: 13/03/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002241663
Claimant Vehicle No :	SLJ8724Y	Insured Vehicle No :	SKE8343B
Date of Loss:	10/11/2022	Nature of Claim:	TP
		Claim No:	202222008184

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ8724Y	Engine No:	G4FGGU259678
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMHU290538
Reg. Date:	29/12/2016 (Man. Year: 2016)	Odometer:	99521 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,332.96	2,597.20	735.76	22.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,720.00	1,480.00	46.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,532.96	4,317.20	2,215.76	33.92
+ GST 8.00/8.00% (S\$)	522.64	345.38	177.26	33.92
Nett Amount (S\$)	7,055.60	4,662.58	2,393.02	33.92
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
	Nett Liability (S\$)	4,902.58		

INSPECTION

Date of Assignment:	17/11/2022		
Date Inspected:	24/11/2022	Inspected At:	Komoco Motors Pte Ltd (HQ) 253 ALEXANDRA ROAD, #01-01 Singapore 159936
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Mar 2023)
Parts: 143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLJ8724Y)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	10		*FRONT BUMPER CLIP	Necessary	12.00 FL	*12.00 FL	
2	1		*COVER ASSY -RR BPR UNDER	Not Necessary	37.20 FL	*- FL	
3	1		*COVER -RR BUMPER LWR	Deformed	250.10 FL	*250.10 FL	
4	1		*REFLECTOR /REFLEX ASSY -RR LH	Cracked	40.80 FL	*40.80 FL	
5	1		*REFLECTOR /REFLEX ASSY -RR RH	Cut	40.80 FL	*40.80 FL	
6	1		*COVER ASSY -RR BUMPER UPR	Cracked	481.40 FL	*481.40 FL	
7	1		*BEAM -RR BUMPER	Bent	294.80 FL	*294.80 FL	
8	1		*WEATHER STRIP-TRUNK LID	Not Necessary	92.50 FL	*- FL	
9	1		*TRIM ASSY -TRUNK LID	Not Necessary	146.80 FL	*- FL	
10	1		*PANEL ASSY -BACK	Repair	454.60 FL	*- FL	
11	1		*PANEL ASSY -TRUNK LID	Bent	2,049.80 FL	*2,049.80 FL	
12	1		*PANEL ASSY -TRUNK LID ,LH	Not Necessary	94.30 FL	*- FL	
13	1		*PANEL ASSY -TRUNK LID ,RH	Not Necessary	94.30 FL	*- FL	
14	1		*SYMBOL MARK -H	Necessary	28.00 FL	*28.00 FL	
15	1		*EMBLEM -ELANTRA	Necessary	48.80 FL	*48.80 FL	
					Sub Total (S\$)	4,166.20	3,246.50
					- List Item Discount on L Items 20.00/20.00% (S\$)	833.24	649.30
					Total Parts (S\$)	3,332.96	2,597.20

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT ACCIDENT BODY REPAIR	New	1,520.00	760.00
2	COMPLETE PUTTY AND SPRAY PAINT ALL AFFECTED AREAS	New	1,400.00	680.00
3	TO SUPPLY BONNET /TRUNK/DOOR SEALANT	New	100.00	100.00
4	TO TRANSFER TRUNK MECHANISM	New	180.00	180.00
			Gross Labour Cost (\$\$)	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >