

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SEOW MEI FONG
BLK 622 BUKIT BATOK CENTRAL #18-502
SINGAPORE 650622

Contact : 97548818, 98178818

TAX INVOICE

Repair Code : CLM15722

Date in : 16/11/2022

Vehicle Num. : SMF5700U

Model : HONDA CIVIC 1.5 TURBO VTIS SR

Chassis/Eng# : MRHFC1660JT000012/L15B73621181

T? Allianz
Xiao Tony

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>dent</i>	1	684.50	✓ 684.50
REAR BOOTLID 'CIVIC' EMBLEM	1	31.50	✓ 31.50
REAR BOOTLID 'I-VTEC' EMBLEM	1	34.20	✓ 34.20
REAR BOOTLID 'LOGO' EMBLEM	1	28.00	✓ 28.00
REAR BOOTLID HINGES GARNISH L/R <i>new</i>	2	124.30	+ 248.60
REAR BOOTLID HINGES L/R <i>new</i>	2	49.20	+ 98.40
REAR BOOTLID INNER RUBBER STOPPER L/R <i>new</i>	2	9.80	+ 19.60
REAR BOOTLID INNER TRIM BOARD <i>new</i>	1	105.60	+ 105.60
REAR BOOTLID LOCK STRIKER <i>new</i>	1	49.20	+ 49.20
REAR BOOTLID MECHANISM LOCK <i>new</i>	1	84.90	✓ 84.90
REAR BOOTLID NUMBER PLATE LAMP L/R <i>new</i>	2	88.70	+ 177.40
REAR BOOTLID OUTER GARNISH <i>new</i>	1	268.00	✓ 268.00
REAR BOOTLID OUTER LOCK SWITCH <i>new</i>	1	128.00	+ 128.00
REAR BOOTLID REFLECTOR L/R <i>at</i>	2	133.60	✓ 267.20
REAR BOOTLID WEATHER STRIP <i>at</i>	1	80.40	✓ 80.40
REAR BUMPER <i>Dehd</i>	1	617.20	✓ 617.20
REAR BUMPER LOWER COVER (EXHAUST) L/R <i>torn</i>	2	60.40	✓ 120.80
REAR BUMPER LOWER LID (BLACK) <i>Dehd</i>	1	198.10	✓ 198.10

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

SEOW MEI FONG
 BLK 622 BUKIT BATOK CENTRAL #18-502
 SINGAPORE 650622

Contact : 97548818, 98178818

TAX INVOICE

Repair Code : CLM15722

Date in : 16/11/2022

Vehicle Num. : SMF5700U

Model : HONDA CIVIC 1.5 TURBO VTIS SR

Chassis/Eng# : MRHFC1660JT000012/L15B73621181

REAR BUMPER REFLECTOR GARNISH L/R	cut	2	31.50	✓	63.00
REAR BUMPER REFLECTOR L/R	cut	2	24.50	✓	49.00
REAR BUMPER REINFORCEMENT	Dented	1	288.40		288.40
REAR BUMPER REVERSE SENSOR	2 pieces damaged	4	149.20		596.80 298.40
REAR BUMPER REVERSE SENSOR 'O' RING	new	4	15.00	✓	60.00
REAR BUMPER REVERSE SENSOR HOLDER	new	4	18.00	✓	72.00
REAR BUMPER REVERSE SENSOR WIRE HARNESS	new	1	87.40	+	87.40
REAR BUMPER SIDE RETAINER L/R	cut	2	75.40	✓	150.80
REAR BUMPER TOW HOOK COVER	new	1	20.00	✓	20.00
REAR END PANEL	Dented	1	377.50	✓	377.50
REAR END PANEL ANTENNA SENSOR	✓	1	80.40	✓	80.40
REAR END PANEL BUZZLE SENSOR	✓	1	85.10	✓	85.10
REAR END PANEL INNER TOP GARNISH	cracked	1	70.30	✓	70.30
REAR FENDER INNER TRIM BOARD L/R	new	2	269.30	✓	538.60
REAR FLOOR PANEL TOP BOARD COVER	torn	1	255.40	✓	255.40
REAR TAILLAMP INNER PANEL L/R	Repair	2	68.90	+	137.80
REAR TAILLAMP L/R	cut	2	298.40	✓	596.80
REAR TAILLAMP LOWER BRACKET L/R	cut	2	19.40	✓	38.80

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

SEOW MEI FONG
 BLK 622 BUKIT BATOK CENTRAL #18-502
 SINGAPORE 650622

Contact : 97548818, 98178818

TAX INVOICE

Repair Code : CLM15722

Date in : 16/11/2022

Vehicle Num. : SMF5700U

Model : HONDA CIVIC 1.5 TURBO VTIS SR

Chassis/Eng# : MRHFC1660JT000012/L15B73621181

		Subtotal before discount	4900.70	6,809.70
Percentage discount 20%			3920.56	1,361.94
		Sub-total 1		5,447.76
REAR BOOTLID CAMERA	new	1	800.00	+ 800.00
REAR BOOTLID INNER TRIM BOARD CLIPS - SET	new	1	50.00	+ 50.00
REAR BOOTLID NUMBER PLATE	green	1	25.00	+ 25.00
REAR BOOTLID NUMBER PLATE HOLDER		1	50.00	+ 50.00
REAR BOOTLID OUTER GARNISH CLIPS - SET	new	1	50.00	30 50.00
REAR BOOTLID TOP SPOILER	cutted	1	1200.00	700 1,200.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	new	1	40.00	20 40.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	new	2	50.00	80 100.00
REAR TAILLAMP CLIPS L/R - SET	new	2	25.00	20 50.00
REAR FENDER CLIPS - SET	new	1	80.00	30 80.00
Super		Subtotal before discount		2,445.00
Percentage discount 0%				0.00
		Sub-total 2		2,445.00
		Parts-total		7,892.76

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SEOW MEI FONG
BLK 622 BUKIT BATOK CENTRAL #18-502
SINGAPORE 650622

Contact : 97548818, 98178818

TAX INVOICE

Repair Code : CLM15722

Date in : 16/11/2022

Vehicle Num. : SMF5700U

Model : HONDA CIVIC 1.5 TURBO VTIS SR

Chassis/Eng# : MRHFC1660JT000012/L15B73621181

LABOUR

To transfer rear bootlid mechanism lock outer handle reflector

60 80.00

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

✓ 80.00

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

60 100.00

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

1860

8w 1,300.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

8w 1,000.00

To apply anti-rust chemical on repaired and replaced panel.

60 120.00

Labour Total

2,680.00

Parts & Labour Total

10,572.76

*** This is a computer-generated document which requires no signature.***

page 4

Adnan C
C/S 18/11/22.

068up.

total: 6580.56

C/S SJK ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: