

ASS. REC. BY:

REF: A161Kenneth

## ASSIGNMENT

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Trans Cab

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 843,164/2

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: SHD 530114Yr Regn: 01, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toy Priusc.c. 1798Colour M.P. White / Red

A/C: Insured / Std / NI / NA

Sp. Reading 309P53

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDKB31F-U-X 03078864Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/m or

Tyre Size: F: Wanli 195/65R15R: Pailan

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 2 mmR/Bal. 4 mmL/Bal. 2 mmL/Bal. 4 mmD.O.A. 16/11/22D.O.I. 16/11/2022

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prell. Report  
☐ : Final Report
1) \_\_\_\_\_  
Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

- ☐
- : Site Insp (\$)
- 
- ☐
- : Interview (\$)
- 
- ☐
- : Tech Invs (\$)
- 
- ☐
- : Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

F. P. X

Others

Report Format:

Lump Sum / I.B.I. (\$) \_\_\_\_\_

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5301H**

*Not Notation* AAD2211-072  
*6/1/2022*

Vehicle No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**1 6 NOV 2022****SHD5301H**

200303878K

TOYOTA

PRIUS

16/11/2022

**SJZ9063D / AIG**

11/1/2019

**PART****LIST**

1 COVER, REAR BUMPER	\$	<i>R</i>	442.60	—
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>R</i>	332.70	—
1 COVER, REAR BUMPER, LOWER	\$	<i>Chis</i>	15.40	—
1 GUARD, REAR BUMPER, CENTER	\$	<i>CM</i>	576.30	—
1 RETAINER, REAR BUMPER SIDE, LH	\$	<i>Sn</i>	116.50	X
1 RETAINER, REAR BUMPER SIDE, RH	\$	<i>Dir</i>	117.70	—
1 RETAINER, REAR BUMPER SIDE, LH	\$	<i>Dir</i>	116.50	—
1 RETAINER, REAR BUMPER SIDE, RH	\$	<i>Sn</i>	117.70	X
1 FILLER, REAR BUMPER EXTENSION, RH	\$	<i>mgcm</i>	123.70	—
1 FILLER, REAR BUMPER EXTENSION, LH	\$	<i>h</i>	123.70	—
1 PANEL SUB-ASSY, BACK DOOR	\$	<i>R</i>	1,147.80	—
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	<i>mgcm</i>	925.60	—
1 BOARD ASSY, BACK DOOR TRIM	\$	<i>Sn</i>	259.20	X
1 WEATHERSTRIP, BACK DOOR	\$	<i>Sn</i>	372.30	X
1 BOARD, BACK DOOR TRIM	\$	<i>Sn</i>	225.20	X
1 LENS & BODY, REAR COMBINATION LAMP, LH (UPPER)	\$	<i>Sn</i>	443.30	X
1 LENS AND BODY, REAR LAMP, LH (LOWER)	\$	<i>Sn</i>	502.00	X
1 LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)	\$	<i>Sn</i>	443.30	X
1 LENS AND BODY, REAR LAMP, RH (LOWER)	\$	<i>Sn</i>	502.00	X
1 BOX, DECK FLOOR, RH	\$	<i>Sn</i>	313.60	X
1 BOX, DECK FLOOR, LH	\$	<i>Sn</i>	313.00	X
1 BOARD, REAR FLOOR, NO.1	\$	<i>Return</i>	519.00	—
1 BOX, DECK FLOOR, REAR	\$	<i>Sn</i>	105.80	X
1 PANEL ASSY, DECK TRIM SIDE, LH	\$	<i>R</i>	355.90	X
1 PANEL ASSY, DECK TRIM SIDE, RH	\$	<i>R</i>	355.90	X
1 COVER, FLOOR UNDER, NO.1 LH	\$	<i>cm</i>	175.10	—
1 COVER, FLOOR UNDER, NO.2 RH	\$		241.90	?
1 COVER, REAR FLOOR CTR	\$	<i>mir</i>	229.90	—



**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5301H**

AAD2211-072

1	COVER, DECK TRIM, REAR	\$	126.70 X
1	PAN, REAR FLOOR	\$	583.40 X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	650.30 ✓
1	LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH	\$	467.00 X
1	SWITCH ASSY, BACK DOOR OPENER	\$	179.10 X
1	SEAL, REAR BUMPER SIDE, LH	\$	88.50 X
1	SEAL, REAR BUMPER SIDE, RH	\$	88.50 X
1	DUCT ASSY, QUARTER VENT, LH	\$	67.00 X
1	DUCT ASSY, QUARTER VENT, RH	\$	67.00 X
1	SPOILER, SUB ASSY, REAR	\$	1,575.40 X
1	GLASS, BACK WINDOW FIX	\$	761.40 X
1	MOULDING, BACK WINDOW, LOWER NO.2	\$	23.60 ✓
1	MOULDING, BACK WINDOW, OUTSIDE LH NO.2	\$	30.90 ✓
1	MOULDING, BACK WINDOW, OUTSIDE RH NO.2	\$	30.90 ✓
1	DAM, BACK DOOR GLASS ADHESIVE, NO.2	\$	28.90 ✓
1	STAY ASSY, BACK DOOR, LH	\$	242.50 X
1	STAY ASSY, BACK DOOR, RH	\$	242.50 X
1	HINGE ASSY, BACK DOOR, LH	\$	61.00 X
1	HINGE ASSY, BACK DOOR, RH	\$	61.00 X
1	REAR TAILGATE TOYOTA LOGO	\$	47.90 ✓
1	REAR TAILGATE WORDING 'PRIUS'	\$	54.60 ✓
1	REAR TAILGATE WORDING 'HYBRID'	\$	54.60 ✓
1	PANEL SUB-ASSY, QUARTER LH	\$	871.50 X
1	PANEL SUB-ASSY, QUARTER RH	\$	871.50 X
1	CARRIER, SPARE WHEEL, NO.1	\$	20.80 X
1	COVER, FRONT BUMPER	\$	516.00 ✓
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	103.40 X
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	716.60 X
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	246.10 X
1	ABSORBER, FRONT BUMPER, LOWER	\$	132.70 X
1	ABSORBER, FRONT BUMPER ENERGY	\$	79.60 X
1	SUPPORT, FRONT BUMPER SIDE, RH	\$	80.10 ✓
1	SUPPORT, FRONT BUMPER SIDE, LH	\$	82.30 X
1	EXTENSION, FRONT BUMPER, RH	\$	120.10 X
1	EXTENSION, FRONT BUMPER, LH	\$	120.10 X
1	COVER, FRONT BUMPER HOLE, RH	\$	29.30 ✓
1	UNIT ASSY, HEADLAMP, LH	\$	2,637.60 ✓
1	UNIT ASSY, HEADLAMP, RH	\$	2,637.60 ✓

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5301H****AAD2211-072**

- 1 GRILLE SUB-ASSY, RADIATOR
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 EMBLEM ASSY, RADIATOR GRILLE
- 1 FENDER SUB-ASSY, FRONT RH
- 1 LINER, FRONT FENDER, RH
- 1 EMBLEM, SIDE PANEL
- 1 FENDER SUB-ASSY, FRONT LH
- 1 LINER, FRONT FENDER, LH
- 1 EMBLEM, SIDE PANEL
- 1 SUPPORT, RADIATOR, UPPER RH
- 1 SUPPORT, RADIATOR, UPPER LH
- 1 SUPPORT SUB-ASSY, RADIATOR, UPPER
- 1 SUPPORT SUB-ASSY, RADIATOR, LOWER
- 1 SUPPORT SUB-ASSY, RADIATOR, LH
- 1 SUPPORT SUB-ASSY, RADIATOR, RH
- 1 HOOD SUB-ASSY
- 1 HINGE ASSY, HOOD, LH
- 1 HINGE ASSY, HOOD, RH
- 1 BRACE, HOOD LOCK SUPPORT
- 1 INSULATOR, HOOD
- 1 LOCK ASSY, HOOD
- 1 SEAL, HOOD TO FRONT END PANEL
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 CONDENSER ASSY, COOLER
- 1 CLEANER ASSY, AIR
- 1 BRACKET, HEADLAMP, LH
- 1 BRACKET, HEADLAMP, RH
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 BRACKET, FRONT BUMPER SIDE, RH
- 1 COVER, RADIATOR SUPPORT OPENING

\$	CM	346.00	✓
\$	Sm	170.10	X
\$	Pr	90.80	✓
\$	R	977.80	X
\$	Pl	206.70	X
\$	na	54.60	X
\$	R	977.80	X
\$	Sm	202.50	X
\$	na	54.60	X
\$	Ry	78.90	✓
\$	R	78.90	X
\$	Bu	377.10	✓
\$		409.90	?
\$		245.10	?
\$		245.10	?
\$	Bu	983.10	✓
\$	R	58.90	X
\$	R	58.90	X
\$	Diy	78.30	✓
\$	Sm	410.90	X
\$	Diy	135.00	✓
\$	R	51.60	X
\$	Pl	219.10	X
\$		1,783.20	?
\$		1,147.00	?
\$	Pl	34.80	X
\$	Pl	34.80	X
\$	Pl	59.30	X
\$	Pl	59.30	X
\$	Pl	235.30	X

TOTAL	\$	34,177.00
25%	\$	8,544.25
	\$	25,632.75

**Special Nett**

1SET PARKING AID

\$ 700.00 2201AC-



**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5301H****AAD2211-072**

1SET REAR BUMPER CLIP	\$	Mr 95.00 60sm
2 WINDSCREEN SEALANT	\$	Mr 150.00 80sm
1 WINDSCREEN MOULDING	\$	Mr 200.00
1 WINDSCREEN INNER SPONGE SEAL	\$	Mr 130.00 30sm
1 REAR TAILGATE STICKER "Trans-Cab"	\$	Mr 80.00 30sm
1 REAR TAILGATE STICKER "6555-3333"	\$	Mr 80.00 30sm
1 REAR BUMPER PROTECTOR	\$	Mr 180.00 30sm
2 SEAM SEALANT	\$	Mr 250.00 X
1SET REAR BUMPER RETAINER CLIP	\$	Mr 85.00 X
1 REAR NUMBER PLATE WITH HOLDER	\$	Mr 140.00 X
1SET TAILLAMP LOWER CLIP	\$	Mr 55.00 X
1SET TAILLAMP UPPER CLIP	\$	Mr 55.00 X
1 END PANEL TRIM CLIP	\$	Mr 65.00 X
1 REAR SPOILER CLIP	\$	Mr 70.00 X
1SET BUMPER CLIP FRT	\$	Mr 95.00 60sm
1 FRONT NUMBER PLATE WITH MOULDING	\$	Mr 200.00 85sm
1SET CLIP, FRONT FENDER LINER	\$	Mr 85.00 X
1SET FRNT BUMPER RETAINER CLIP	\$	Mr 85.00 X
1 HOOD INSULATOR CLIP	\$	Mr 55.00 X

<b>TOTAL</b>	<b>\$</b>	<b>2,855.00</b>
--------------	-----------	-----------------

<b>TOTAL PARTS</b>	<b>\$</b>	<b>28,487.75</b>
--------------------	-----------	------------------

**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$	1801	300.00
----	------	--------

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	601	380.00
----	-----	--------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$	12001	3,000.00
----	-------	----------

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$	Mr	380.00 X
----	----	----------

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5301H****AAD2211-072**

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00	601
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn 480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	1001
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	901
Towing Fees	\$	150.00	501
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	15401
To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	170.00	401
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 220.00	X
To replace, refix and top up coolant for radiator	\$	170.00	501
To lift-up / out engine with gear box and refit.	\$	nn 440.00	X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5301H**

To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.

\$ *nn* 380.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.

\$ *nn* 380.00 X

**TOTAL** \$ 11,890.00

**Over All Total** \$ 40,377.75

**(LUMP SUM) Repair Days**

~~25 DAYS~~

*10 days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		Company
Owner ID Type:		878K
Owner ID:		
Vehicle Details		SHD5301H
Vehicle No.:		Yes
Vehicle to be Exported:		16 Nov 2022
Intended Deregistration Date:		TOYOTA
Vehicle Make:		PRIUS 5DR HATCHBACK (AUTO)
Vehicle Model:		Red
Primary Colour:		2018
Manufacturing Year:		2ZR2B95613
Engine No.:		JTDKB3FUX03078864
Chassis No.:		90.0 kW (120 bhp)
Maximum Power Output:		\$26,605.00
Open Market Value:		11 Jan 2019
Original Registration Date:		11 Jan 2019
First Registration Date:		0
Transfer Count:		\$14,247.00
Actual ARF Paid:		
Intended PARF Rebate Details		
PARF Eligibility:		Yes
PARF Eligibility Expiry Date:		10 Jan 2027
PARF Rebate Amount:		\$10,685.00
Intended COE Rebate Details		
COE Expiry Date:		10 Jan 2027
COE Category:		A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):		8
PQP Paid:		\$20,838.00
COE Rebate Amount:		\$10,811.00
Total Rebate Amount:		\$21,496.00

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 16 Nov 2022

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	16/11/2022 12:13 (SGT)
Reported by	Driver
Date of Accident	16/11/2022 11:00 (SGT)
Exact Location of Accident	Near 130 Kim Tian Rd, Block 130, Singapore 160130
Additional Location Information	CTE TOWARDS SLE AFTER JLN BUKIT MERAH
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD5301H
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Company Reg No	2XXXXX878K
Email Address	claims@transcab.com.sg
Mobile Phone No	(Phone) +65-62876666
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1798

### INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Policy Number / Cover Note Number	VFX/P2413997

### DRIVER

Name of Driver	NG CHOON HUAT
NRIC No	SXXXX125C
Date Of Birth	23/04/1951
Occupation	Outdoor

Date Of Driving Pass  
Driving experience  
Gender  
Mobile Number  
Alt. Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

27/09/1971  
51 YEARS AND 2 MONTHS  
Male  
(Phone) +65-93873291  
-  
claims@transcab.com.sg  
329 TAH CHING ROAD  
#21-92  
610329  
No  
Hirer  
No  
-  
-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
Weather Conditions  
Road Surface

Chain Collision  
Clear  
Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? No  
Number of vehicles involved in the accident 3  
Was anybody injured in the Accident? No  
Was any injured conveyed to hospital by ambulance? -  
Was any other vehicle or property damaged? Yes  
Number of Passengers (Including Driver) 2  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No  
Translator's name -  
Translator's ID -  
Translator's phone number -  
Translator's email -  
Original language used in the statement -

#### PASSENGER 1

Name P1  
Gender Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? No  
Was notice of intended Prosecution given? No  
If yes, against whom? -

#### CIRCUMSTANCES OF ACCIDENT

ON 16/11/2022 AT ABOUT 1100HOURS, I WAS TRAVELLING ALONG CTE TOWARDS SLE. WHEN I SAW VEHICLE B JAMMED BRAKE, I APPLIED MY BRAKE AND STOPPED IN TIME. SUDDENLY I FELT AN IMPACT FROM MY REAR AND MY VEHICLE HIT ONTO REAR OF VEHICLE C.

#### ATTACHMENT(S)

Are accident photos available for attachment? Yes  
Was there any video captured by Car Camera? Yes  
Reasons for not uploading a video of the accident WITH TRANSCAB.

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJZ9063D



Vehicle Manufacturer	Toyota
Vehicle Model	Vios
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name Of Driver	KWONG KOON SHING
NRIC No	SXXXX590I
Contact Number	(Phone) +65-97260864
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMC3816Z
Vehicle Manufacturer	Nissan
Vehicle Model	QASHQAI
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name Of Driver	LIM HUI MEI CINDY
NRIC No	SXXXX031C
Contact Number	(Phone) +65-96360429
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



C. SAC 38/62

On

卷之四

Witnessed By Reporting Officer  
Vikram J. K. K.