

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0995/2022/EQ
DATE : 11-Nov-22
WIP : 50012

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/11/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR WONG TUCK HUEI
ADDRESS : BLK 159 YISHUN STREET 11
#08-174
SINGAPORE 760159
TELEPHONE : HP +65 91847672
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900235910-03
VEHICLE NO : **SMQ 1942 G**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 31/10/2019
ENGINE NO : CHZ C31207
CHASSIS NO : WAUZZZ8V8KA096455
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Nov-22
PLACE OF ACCIDENT : JOO CHIAT LANE TO JOO CHIAT ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 1942 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	1000-
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ 2,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,002.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 1942 G

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Reband</i>	1	\$ 2,432.00	✓	
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 195.00	+	
3	FRONT BUMPER GUIDE SECTION - LH <i>?</i>	1	\$ 43.00	?	
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 179.00	+	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 571.00	+	
6	FRONT BUMPER CLOSING ELEMENT - LH <i>new</i>	1	\$ 318.00	+	
7	FRONT BUMPER TRIM COVER - LH <i>new</i>	1	\$ 182.00	+	
8	FRONT WHEEL HOUSING LINER ADAPTER - LH <i>new</i>	1	\$ 42.00	+	
9	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	1	\$ 210.00	+	
10	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	1	\$ 211.00	+	
11	FRONT BUMPER REINFORCEMENT BEAM COVER <i>new</i>	1	\$ 136.00	+	
12	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$ 847.00	+	
13	FRONT FENDER - LH <i>Dented</i>	1	\$ 954.00	✓	
14	FRONT FENDER RIVET <i>ru</i>	5	\$ 19.00	✓	
15	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 75.00	+	
16	FRONT FENDER BRACKET - LH <i>?</i>	1	\$ 46.00	?	
17	FRONT FENDER BRACE <i>?</i>	1	\$ 107.00	?	
18	FRONT WHEEL HOUSING LINER - LH <i>new</i>	1	\$ 183.00	+	
19	HEADLIGHT - LH <i>lit</i>	1	\$ 5,879.00	✓	
20	HEADLIGHT HOSE - LH <i>new</i>	1	\$ 46.00	+	
SUB TOTAL SPARE PARTS			\$ 12,675.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 1942 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	LIFT CYLINDER - LH <i>2 Extra</i>	1	\$ 156.00	?
22	LIFT CYLINDER HOSE <i>Not m</i>	1	\$ 78.00	+
23	OUTSIDE TEMPERATURE SENSOR BRACKET <i>not use</i>	1	\$ 21.00	x
24	RADIATOR AIR GUIDE - LH <i>not use</i>	1	\$ 28.00	+
25	LIFT CYLINDER WASH WATER RESERVOIR <i>Not m</i>	1	\$ 226.00	+ +
26	SUNDRIES		\$ 400.00	?
TOTAL SPARE PARTS		:	\$ 13,584.00	
TOTAL LABOUR CHARGES		:	\$ 5,002.00	
GRAND TOTAL		:	\$ 18,586.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Adrian King

SURVEYED DATE

: 15/11/22

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

: Not Authorised, 04 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT