

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0995/2022/EQ
DATE : 11-Nov-22
WIP : 50012

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/11/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

4 days - ok - Johnny Boo

24-Mar-23

OWNER'S NAME : MR WONG TUCK HUEI
ADDRESS : BLK 159 YISHUN STREET 11
#08-174
SINGAPORE 760159
TELEPHONE : HP +65 91847672
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900235910-03
VEHICLE NO : **SMQ 1942 G**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 31/10/2019
ENGINE NO : CHZ C31207
CHASSIS NO : WAUZZZ8V8KA096455
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Nov-22
PLACE OF ACCIDENT : JOO CHIAT LANE TO JOO CHIAT ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 1942 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$ 250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$ 1,000.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,000.00	\$ 1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	5,002.00	\$ 2,542.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG
MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 1942 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,432.00	\$	1,945.60
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00		
3	FRONT BUMPER GUIDE SECTION - LH	1	\$ 43.00	\$	34.24
4	FRONT BUMPER GRILLE - CENTER	1	\$ 179.00		
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 571.00		
6	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 318.00		
7	FRONT BUMPER TRIM COVER - LH	1	\$ 182.00		
8	FRONT WHEEL HOUSING LINER ADAPTER - LH	1	\$ 42.00		
9	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 210.00		
10	FRONT BUMPER FOAM FILLER PIECE	1	\$ 211.00	\$	168.80
11	FRONT BUMPER REINFORCEMENT BEAM COVER	1	\$ 136.00		
12	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 847.00	\$	677.20
13	FRONT FENDER - LH	1	\$ 954.00	\$	763.20
14	FRONT FENDER RIVET	5	\$ 19.00	\$	15.20
15	FRONT FENDER ATTACHMENT PARTS	1	\$ 75.00		
16	FRONT FENDER BRACKET - LH	1	\$ 46.00		
17	FRONT FENDER BRACE	1	\$ 107.00	\$	85.60
18	FRONT WHEEL HOUSING LINER - LH	1	\$ 183.00		
19	HEADLIGHT - LH	1	\$ 5,879.00	\$	4,703.20
20	HEADLIGHT HOSE - LH	1	\$ 46.00		
SUB TOTAL SPARE PARTS		:	\$ 12,675.00	\$	8,393.04

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 1942 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>8,393.04</i>
21	LIFT CYLINDER - LH	1	\$ 156.00		
22	LIFT CYLINDER HOSE	1	\$ 78.00		
23	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00		
24	RADIATOR AIR GUIDE - LH	1	\$ 28.00		
25	LIFT CYLINDER WASH WATER RESERVOIR	1	\$ 226.00	<i>\$</i>	<i>184.40</i>
26	ADD PARTS		<i>\$ 224.50</i>	<i>\$</i>	<i>179.60</i>
27	SUNDRIES		\$ 400.00		
TOTAL SPARE PARTS			\$ 13,808.50	<i>\$</i>	<i>8,757.04</i>
TOTAL LABOUR CHARGES			\$ 5,002.00	<i>\$</i>	<i>2,542.00</i>
GRAND TOTAL			\$ 18,810.50	<i>\$</i>	<i>11,299.04</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-15/03/23

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0995/2022/EQ 24-Mar-23 CHANG/JB 1 of 1 SMQ1942G AUDI A3 SEDAN 1.0
Quantity	Description		Unit Price
<u>Parts</u>			
1	horn		\$ 224.50
	GRAND TOTAL		\$ 224.50

For Premium

Authoriser

TFSI	
Amount	
\$	179.60
\$	179.60

Automobiles Pte Ltd

Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT