

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0998/2022/EQ
DATE : 14-Nov-22
WIP : 50040

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/11/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHIN LI CHOONG
ADDRESS : 25 WATTEN CLOSE
SINGAPORE 287747

TELEPHONE : HP +65 98789689
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900167067-03
VEHICLE NO : **SGB 7911 G**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 27/9/2019
ENGINE NO : CVK 082422
CHASSIS NO : WAUZZZF4XKA076119
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 9-Nov-22
PLACE OF ACCIDENT : WEST COAST TURN INTO ALEXANDRA ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGB 7911 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00 ✗	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00 ✓	500
4	TO RESPRAY FRONT BUMPER.	\$ 900.00 ✓	550
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 3,322.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGB 7911 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>2-5</i> torn ✓	1	\$ 2,377.00 ✓	1901.60
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 612.00 ✗	
3	FRONT BUMPER SECURING STRIP - LH / RH <i>new</i>	2	\$ 79.00 ✗	
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 219.00 ✗	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 254.00 ✗	
6	FRONT BUMPER AIR GUIDE - LH / RH new lh dm	2	\$ 144.00 ✓	57.20
7	RADIATOR GRILLE <i>new</i>	1	\$ 1,478.00 ✓	1182.40
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2	\$ 302.00 ✗	
9	FRONT BUMPER FOAM FILLER PIECE	1	\$ 139.00 ✗	
10	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$ 899.00 ✗	
11	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 82.00 ✗	
12	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 143.00 ✗	
13	CAUTION SIGN STICKER	1	\$ 16.00 ✗	
14	AIR CONDITIONER STICKER <i>new</i>	1	\$ 9.00 ✗	
15	FRONT BUMPER BRACKET	1	\$ 154.00 ✗	
16	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00 ✗	
17	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 531.00 ✗	
18	FRONT PARKING AID SEAL RING	4	\$ 10.00 ✗	
19	HORN HIGH TONE - LH	1	\$ 134.00 ✗	
20	HORN LOW TONE - RH	1	\$ 139.00 ✗	
SUB TOTAL SPARE PARTS		:	\$ 7,785.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGB 7911 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN BRACKET - LH / RH	2	\$ 66.00	X
22	HEADLIGHT - LH / RH	2	\$ 16,588.00	X
23	LIFT CYLINDER - LH / RH	2	\$ 462.00	X
24	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00	X
25	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	X
26	RADIATOR AIR GUIDE - LH / RH INNER	2	\$ 64.00	X
27	RADIATOR AIR GUIDE - LH / RH OUTER	2	\$ 28.00	X
28	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 44.00	X
29	FRONT NOISE INSULATION	1	\$ 640.00	X
30	FRONT NO PLATE	S/N	\$ 60.00	X
31	SUNDRIES		\$ 400.00	2.88
TOTAL SPARE PARTS			\$ 26,265.00	
TOTAL LABOUR CHARGES			\$ 3,322.00	
GRAND TOTAL			\$ 29,587.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adnan
SURVEYED DATE : 16/11/22
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 03 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT