

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22011608/ANCE2**Date:** 04/05/2023**REFERENCE**

Insured/Claimant:	NEO DANIEL	Policy No:	7220039070	
Date of Loss:	14/11/2022	Nature of Claim:	OD	Claim No: 7511943647SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNE8022S	Engine No:	DKY016437
Make & Model:	AUDI A6 DESIGN, 2.0 TFSI (140 KW) (A)	Chassis No:	WAUZZZF24NN008958
Reg. Date:	11/04/2022 (Man. Year: 2021)	Odometer:	5715 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$280,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,132.00	6,483.92	5,648.08	46.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,142.00	1,672.00	3,470.00	67.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,274.00	8,155.92	9,118.08	52.78
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	16,474.00	7,355.92	9,118.08	55.35
+ GST 8.00/8.00% (S\$)	1,317.92	588.47	729.45	55.35
Nett Amount (S\$)	17,791.92	7,944.39	9,847.53	55.35

INSPECTION

Date of Assignment:	18/11/2022		
Date Inspected:	16/11/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -LH	Dented	4,489.00 FS	*3,591.20 FS
2	1		*FRONT OUTER DOOR SEAL -LH	Necessary	191.00 FS	*152.80 FS
3	1		*FRONT DOOR CATCH -LH	Not Necessary	134.00 FS	*- FS
4	1		*FRONT EXTERIOR WING MIRROR MOUNTING -LH	Damaged	3,069.00 FS	*2,455.20 FS
5	1		*FRONT WING MIRROR CAP -LH	Damaged	348.00 FS	*278.00 FS
6	1		*FRONT WING MIRROR GLASS -LH	Not Necessary	1,298.00 FS	*- FS
7	1		*FRONT DOOR HANDLE -LH	Not Necessary	389.00 FS	*- FS
8	1		*FRONT DOOR HANDLE CHROME TRIM PLATE -LH	Not Necessary	109.00 FS	*- FS
9	1		*FRONT DOOR PANEL CAP -LH UPPER	Not Necessary	100.00 FS	*- FS
10	1		*FRONT WINDOW GUIDE CHROME TRIM STRIP -LH	Not Necessary	287.00 FS	*- FS
11	1		*FRONT WINDOW SLOT SEAL CHROME TRIM STRIP -LH OUTER	Not Necessary	224.00 FS	*- FS
12	1		*FRONT WINDOW CORNER TRIM -LH	Not Necessary	87.00 FS	*- FS
13	1		*FRONT WINDOW GUIDE -LH	Not Necessary	542.00 FS	*- FS
14	1		*FRONT DOOR WINDOW -LH	Not Necessary	365.00 FS	*- FS
15	1		*SUNDRIES	Necessary	500.00 FS	*6.72 FS
Total Parts (\$\$)						12,132.00 6,483.92

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	350.00	280.00
2	TO DISMANTLE AND RENEW LHS FRONT DOOR RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY LHS FRONT FENDER ,LHS FRONT DOOR ,DOOR HANDLE AND LHS WING MIRROR COVER	New	3,000.00	700.00
4	TO INSTALL SOLAR FILM ON LHS FRONT DOOR WINDOW GLASS	New	400.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,142.00	1,672.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >