

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Nov 2022)
 Parts: 143 MAZDA 6 2.0 SEDAN STANDARD 2WD (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/SMJ2219S/18/11/2022 09:46-
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Pre - Inspection (Paper Survey by LKK)

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT BUMPER BR	0.00	0.00	✓520.00 F
2	1		*1 PC FRT BUMPER RH RETAINER NEL	0.00	0.00	✓28.00 F
3	1		*6 PCS FRT BUMPER CLIPS @2/PC NEL	0.00	0.00	18 ✓12.00 F 18
4	1		*1 PC RH HEADLAMP Cra	0.00	0.00	✓1,380.00 F
5	1		*1 PC RH HEADLAMP LOWER BRACKET ?	0.00	0.00	✓25.00 F
6	1		*1 PC FRT GRILLE RH CHROME MOULDING ?	0.00	0.00	160 ✓150.00 F 160
7	1		*1 PC FRT RH FENDER Dent	0.00	0.00	✓160.00 F
8	1		*1 PC FRT RH FENDER DUST COVER Dent	0.00	0.00	✓68.00 F
9	1		*6 PCS FRT RH FENDER DUST COVER CLIPS @2/PC NEL	0.00	0.00	18 ✓12.00 F 18
10	1		*1 PC FRT RH WHEEL RIM Scr	0.00	0.00	✓550.00 F
11	1		*1 PC FRT RH LOWER ARM Dent	0.00	0.00	✓230.00 F
12	1		*1 PC FRT RH KNUCKLE Dent	0.00	0.00	✓185.00 F
13	1		*1 PC FRT RH ABSORBER STRUT Dent	0.00	0.00	✓170.00 F
14	1		*1 PC FRT RH ABSORBER STRUT TOP MOUNTING ?	0.00	0.00	✓55.00 F X MW
15	1		*1 PC FRT RH ABSORBER STRUT TOP BEARING ?	0.00	0.00	✓48.00 F X MW
16	1		*1 PC FRT RH STABILIZER LINK ?	0.00	0.00	48 ✓45.00 F Dent 48
17	1		*2 PCS FRT RH STABILIZER BAR BUSHES @35/PC ?	0.00	0.00	X 70.00 F X MW
18	1		*1 PC FRT RH DRIVE SHAFT ?	0.00	0.00	X 600.00 F X MW
19	1		*1 PC FRT RH WHEEL HUB ?	0.00	0.00	✓250.00 F Dent
20	1		*1 PC STEERING TIE ROD RH ?	0.00	0.00	✓65.00 F Dent
21	1		*1 PC STEERING TIE ROD END RH ?	0.00	0.00	✓60.00 F Dent

F=Franchise part

Sub Total (S\$) 4,683.00
 + Margin on L,N Items 10.00% (S\$) 468.30
 Total Parts (S\$) 5,151.30

Cheng Hoe Motor Pte Ltd/SMJ2219S/18/11/2022 09:46. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

* Supp 1pc wiper tank

#70/ Bent ✓

Part #4538 3935
 Supp 70 + 70
 4005
 Add 10% #4108 + 10%
 #410.80
 #1010 4405.50
 #5528.80

SMJ2219S

(72)

Estimates on Miscellaneous Items

Qty	Particulars	Amount
<u>Miscellaneous Items</u>		
1	1 UNIT AUTO TRANSMISSION OIL ?	35.00
Sub Total (\$\$)		35.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TOWING (BY INSURANCE)	New	0.00
2	REMOVE & REPLACE FRT BUMPER, FENDER, HEADLAMPS, & ATTACHMENTS, PANEL BEAT & REPAIR RH FENDER APRON, INNER BRACKETS, HEADLAMP TOP SUPPORT PANEL & REPLACE DAMAGED BODY PARTS	New 500	600.00 400
3	REMOVE & REFIX FRT SUSPENSION / UNDERCARRIAGE AND CHECK STEERING	New 180	250.00 150
4	RESET WHEEL ALIGNMENT	New	80.00 60
5	PUTTY & RESPRAY PAINT ON FRT BUMPER, FRT RH FENDER, FRT TOP PANEL, FRT RH INNER MEMBER	New 600	680.00 400
Gross Labour Cost (\$\$)			1,610.00 1340

Cheng Hoe Motor Pte Ltd/SMJ2219S/18/11/2022 09:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

18/11/22 90097659
LIFE AFTER REPAIR
PIP 5 days. 18/11/22

KKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Complementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

T= 5745.50