

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0885/2022/EQ
DATE : 13-Oct-22
WIP : 45907

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/10/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Adrian

6 days exclude 1 Sunday

Johnny Boo 10 Feb 23

OWNER'S NAME : MS SARAH LAU SHEN YI
ADDRESS : 18 PINE GROVE
#10-02
SINGAPORE 597594
TELEPHONE : HP +65 82237893
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SKS 8399 S**
MODEL CODE : AUDI Q2 1.0 TFSI S-TRONIC
MODEL YEAR : 30/7/2020
ENGINE NO : CHZ C33524
CHASSIS NO : WAUZZZGA7KA084781
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Oct-22
PLACE OF ACCIDENT : BLK 19 GHIM MOH ROAD CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKS 8399 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	280.00	\$ 280.00
2	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI - LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	
3	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	\$ 500.00
4	TO RESPRAY REAR BUMPER, LHS REAR FENDER AND LHS REAR DOOR.	\$	3,000.00	\$ 1,650.00
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	
6	ADDED LABOUR	\$	1,480.00	\$ 830.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	8,432.00	\$ 3,452.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKS 8399 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR DOOR - LH	1	\$ 2,962.00	
2	REAR OUTER DOOR SEAL - LH	1	\$ 151.00	
3	BONDING AGENT	1	\$ 51.00	
4	CLEANING SOLUTION	1	\$ 74.00	
5	APPLICATOR	1	\$ 9.00	
6	REAR DOOR CATCH - LH	1	\$ 134.00	
7	REAR OUTER DOOR SEAL - LH	1	\$ 66.00	
8	REAR DOOR COVER - LH	1	\$ 238.00	\$ 190.40
9	REAR DOOR SIDE MEMBER TRIM - LH	1	\$ 251.00	
10	REAR WHEEL HOUSING LINER - LH		\$ 220.00	
11	REAR ALUMINIUM RIM	1	\$ 1,002.00	
12	REAR ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	
13	REAR BUMPER	1	\$ 1,363.00	
14	REAR BUMPER SPOILER	1	\$ 316.00	\$ 252.80
15	REAR BUMPER REFLECTOR - LH	1	\$ 34.00	
16	REAR BUMPER GUIDE SECTION - LH	1	\$ 60.00	
17	REAR WHEEL COVER - LH / RH	2	\$ 360.00	\$ 287.20
18	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 7,595.00	\$ 730.40
TOTAL LABOUR CHARGES		:	\$ 8,432.00	\$ 3,452.00
GRAND TOTAL		:	\$ 16,027.00	\$ 4,182.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-30/12/22



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0885/2022/EQ 21-Dec-22 Kee Siang 1 of 1 SKS 8399 S AUDI Q2 1.0 TFSI S-TRONIC
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO DISMANTLE FRONT LHS WING MIRROR MOUNTING TO FACILITATE RESPRAY OF FRONT LHS DOOR S/N	\$ 280.00	\$ 280.00
2	TO RESPRAY LHS FRONT DOOR	\$ 1,200.00	\$ 550.00
GRAND TOTAL		\$ 1,480.00	\$ 830.00

For Premium Automobiles Pte Ltd

Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT