

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	ECICS LTD			Ref:	CS/ICS22011614/Avy3	
		Γ CENTRE #09-04A	1	Date:	18/11/2022	
	SINGAPORE 4086	00	(Code:	ICS	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMM 3632J	Veh. Inspected	<u> </u>	SLB 7630H	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	DMPC2200562H/02/CT	Excess (\$)		0.00	
	Assign From	CRYSTABELLE TAN	Assign Date		17/11/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3.						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
5.	General Information				10/11/2000	
	Accident Date	16/11/2022	Inspection Date	•	18/11/2022	
	Survey held at	Divine Splash Spray Painting				
		25 kaki Bukit road 4 #05-36/37 Synergy @ KB S417800				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					