

TP Clinic
Hui Rong

FONG MOTORS				
1 Kaki Bukit Ave 6 #01-27/45				
AutoBay@ Kaki Bukit, Singapore 417883				
Tel: 6748 5648, Email: fongmotors@gmail.com				
Estimate of Cost of Repairs				
		Date	2-Mar-2023	
		Vehicle No.	YQ6972U	
		Model	TOYOTA DYNA	
		CHASSIS/ENG#	JHHAGV4610K002546	
PARTS				
S/N	Item	Quantity	Unit Price	Amount
1	RH DOOR <i>Dented.</i>	1	\$1,941.80	\$1,941.80 1480
2	RH DOOR OUTER HANDLE <i>lit.</i>	1	\$241.00	\$241.00 ✓
3	RH HEAD LAMP <i>lit.</i>	1	\$1,272.30	\$1,272.30 ✓
4	FRONT BUMPER <i>Deformed</i>	1	\$784.90	\$784.90 ✓
5	CORNER PANEL <i>Repair</i>	1	\$526.40	\$526.40 x.
6	STEP GARNISH <i>lit.</i>	1	\$327.70	\$327.70 ✓
7	DOOR BOARD <i>cracked</i>	1	\$531.70	\$531.70 ✓
8	RH DOOR GLASS REGULATOR <i>new</i>	1	\$385.10	\$385.10 x.
9	RH DOOR OUTER RUBBER <i>lit.</i>	1	\$123.20	\$123.20 ✓
10	SIDE MIRROR <i>Damaged</i>	1	\$352.70	\$352.70 ✓
			Sub-total 1	\$6,486.80
NETT ITEMS				
S/N	Item	Quantity	Unit Price	Amount
1	BUMPER CLIP SET <i>new</i>	1	\$50.00	\$50.00 x.
2	STICKER <i>new</i>	1	\$380.00	\$380.00 180
			Sub-total 2	\$430.00
LABOUR				
1	To change door and components			\$120.00 80
2	To knock and change parts			\$600.00 400
3	To conduct wiring checks			\$80.00 30
4	Spray painting on all affected parts			\$600.00 500
			Labour Total	\$1,400.00
			Parts & Labour Total	\$8,316.80

5113.50

3835.12

180

1010

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 5025.12

h/s AK

04 Days

AK