



萬 春 摩 哆

BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GSTReg. No. 351915/00A

GST Regn No. 35191500A

18/11/2022

Lonpac Insurance Berhad
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Attn: Motor Claims Dept.

Dear Sir/Madam

QUOTATION FOR REPAIRS OF VEHICLE NO. GBB 7730 X
MODEL: TOYOTA DYNA
DATE OF ACCIDENT: 16/11/2022
YOUR INSURED VEHICLE REGN NO. XD 3883 T

1 pc	Tailgate	bt ✓
1 pc	Tailboard	Lt ✓ (REAR END PANEL)
1 pc	RH taillamp	scr ✓
1 pc	TOYOTA logo	re ✓
1 pc	DYNA logo	re ✓
1 pc	RH side panel lock	bt ✓

Less: 25% discount

1 pc	70 km/hr sticker	re ✓
1 pc	13 PAX sticker	re ✓

2335.70

25%

1751.77

\$	1,550.40	1455.10
	1,800.30	485.50
	280.30	145.20
	95.30	53.20
	30.20	
	245.30	162.50

\$	4,001.80
	1,000.45
	3,001.35

10	20.00	SN	} 20
10	20.00	SN	

LABOUR CHARGES:

To knocking of straightening of all necessary damaged parts.

To changing of the above parts.

To putty and spray painting on accident damaged parts.

	700.00	500	} 1000
	1,000.00	500	
\$	4,741.35		

Yours faithfully,

Pelinloy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rene

Hf 20010068

5 days

4/5

21/11/22 P1430

Revy after repair