



萬 春 摩 哆
BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GSTReg. No. 351915/00A

GST Regn No. 35191500A

18/11/2022

Lonpac Insurance Berhad
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Attn: Motor Claims Dept.

Dear Sir/Madam

QUOTATION FOR REPAIRS OF VEHICLE NO. GBB 7730 X
MODEL: TOYOTA DYNA
DATE OF ACCIDENT: 16/11/2022
YOUR INSURED VEHICLE REGN NO. XD 3883 T

1 pc	Tailgate	\$	1,550.40
1 pc	Tailboard		1,800.30
1 pc	RH taillamp		280.30
1 pc	TOYOTA logo		95.30
1 pc	DYNA logo		30.20
1 pc	RH side panel lock		245.30
		\$	4,001.80
	Less: 25% discount		1,000.45
			3,001.35
1 pc	70 km/hr sticker		20.00 SN
1 pc	13 PAX sticker		20.00 SN

LABOUR CHARGES:

To knocking of straightening of all necessary damaged parts.

To changing of the above parts.

To putty and spray painting on accident damaged parts.

700.00
1,000.00
<u>\$ 4,741.35</u>

Yours faithfully,

Pelindelo