

ADDRESS: 2 KAKI BUKIT AVENUE 2 AUTOHUB #01-14 SINGAPORE 417921
MOBILE: +65 84404430 - MR LIEW (AH GUO)

TO :	VEHICLE REGISTRATION NO.:	SJD8362M
ATTENTION : MOTOR INSURANCE CLAIM	VEHICLE MAKE/MODEL:	Honda Fit
CLAIM TYPE : 3RD PARTY CLAIM	CHASSIS NUMBER:	GE6-1041831
ACCIDENT DATE/TIME :		

NO.	PARTS	QTY	SPECIAL NETT PRICE
1	Tailgate windscreen glass sealant	1	\$ 40 ✓ 80.00
2	Tailgate windscreen glass inner seal	1	\$ 30 ✓ 50.00
3	Tailgate outer garnish clips	1set	\$ 50.00

4	Tailgate inner trim board clips	1set	\$	20 ✓	60.00
5	End panel inner garnish clips	1set	\$		50.00
6	End panel joint sealant	1	\$	30 ✓	70.00
7	Rear bumper reverse sensor	1set	\$	200 ✓	320.00
8	Rear bumper clips	1set	\$	30 ✓	60.00
9	Rear bumper RH splash shield clips	1set	\$	15 ✓	40.00
10	Rear bumper LH splash shield clips	1set	\$		40.00
11	Rear fender RH inner trim board clips	1set	\$	20 ✓	60.00
12	Rear fender LH inner trim board clips	1set	\$		60.00
13	Rear fender RH joint sealant	1	\$		70.00
14	Rear fender RH glass inner seal	1	\$		50.00
15	Rear fender RH glass inner seal	1	\$		25.00
16	RH taillamp panel joint sealant	1	\$		30.00
17	Rear number plate	1	\$		70.00

385

SPECIAL NETT TOTAL : \$ 1,185.00

NO.	LABOUR CHARGES	AMOUNT
1	Cut/Weld, panel beating, straighten and alignment affected parts and areas. To remove, replace and check items	\$ 1,300.00 800
2	Putty, sand down and re-spray affected areas and parts on the affected areas	\$ 1,200.00 800
3	Check and test wiring system and lighting system	\$ 70.00 30
4	Apply anti-rust coating on replaced and repaired parts and areas	\$ 80.00 60
5	Remove and reinstall tailgate windscreen glass and sealants to assist repair	\$ 200.00 120
6	Remove and reinstall tailgate inner mechanism to new tailgate	\$ 120.00 60
7	Remove and replace tailgate reverse camera to assist repair	\$ 80.00 40
8	Remove and replace rear inner trims, garnish and boards to assist repair	\$ 250.00 60
9	Remove and replace rear bumper reverse sensors to assist repair	\$ 80.00 40
10	Remove and replace exhaust silencer and gasket to assist repair	\$ 180.00 60

2070

LABOUR TOTAL : \$ 3,560.00

5757.96

L/S - 4606.36
= 4600

LIST PRICE: \$ 5,021.84
SPECIAL NETT: \$ 1,185.00
LABOUR: \$ 3,560.00
TOTAL: \$ 9,766.84

5 Days.

Lumpsum Repair

After repair photos.

Gino Qiang

8288 0282

21/11/22.