

S3 AUTO WORKSHOP

ADDRESS: 2 KAKI BUKIT AVENUE 2 AUTOHUB #01-14 SINGAPORE 417921

MOBILE: +65 84404430 - MR LIEW (AH GUO)

ESTIMATED REPAIR CHECKLIST

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TO :
ATTENTION : MOTOR INSURANCE CLAIM
CLAIM TYPE : 3RD PARTY CLAIM
ACCIDENT DATE/TIME :

VEHICLE REGISTRATION NO: SJD8362M
VEHICLE MAKE/MODEL: Honda Fit
CHASSIS NUMBER: GE6-1041831

NO.	PARTS	QTY	LIST PRICE
1	Tailgate / <i>Blue</i>	1	\$ 873.60
2	Tailgate windscreen glass rubber moulding / <i>5 mtl.</i>	1	\$ 126.50
3	Tailgate "Fit" emblem	1	\$ 28.10
4	Tailgate centre emblem	1	\$ 32.00
5	Tailgate outer garnish	1	\$ 141.90
6	Tailgate lock	1	\$ 235.60
7	Tailgate lock catch	1	\$ 29.00
8	Tailgate weatherstrip	1	\$ 153.70
9	Tailgate inner trim board	1	\$ 287.40
10	Rear bumper	1	\$ 512.30
11	Rear bumper RH side retainer	1	\$ 23.10
12	Rear bumper LH side retainer	1	\$ 23.10
13	Rear bumper towing cover	1	\$ 18.00
14	Rear bumper RH splash shield	1	\$ 55.60
15	Rear bumper LH splash shield	1	\$ 55.60
16	RH taillamp assy	1	\$ 387.60
17	RH taillamp sponge gasket	1	\$ 21.00
18	RH taillamp panel	1	\$ 147.00
19	RH taillamp lock clips	1set	\$ 18.00
16	LH taillamp assy	1	\$ 387.60
17	LH taillamp sponge gasket	1	\$ 21.00
18	LH taillamp lock clips	1set	\$ 18.00
17	End panel	1	\$ 412.30
18	End panel inner garnish	1	\$ 79.30
19	Rear fender RH	1	\$ 678.30
20	Rear fender RH glass rubber seal	1	\$ 32.00
21	Rear fender RH inner trim board	1	\$ 213.90
22	Rear fender LH inner trim board	1	\$ 213.90
23	Spare tyre top cover board	1	\$ 292.10
24	Exhaust silencer	1	\$ 613.40
25	Exhaust silencer gasket	1	\$ 45.30
26	Exhaust silencer heat shield	1	\$ 101.10

SUBTOTAL : \$ 6,277.30
LESS 20% : \$ 1,255.46
PARTS TOTAL : \$ 5,021.84

NO.	PARTS	QTY	SPECIAL NETT PRICE
1	Tailgate windscreen glass sealant / <i>5 mtl.</i>	1	\$ 80.00
2	Tailgate windscreen glass inner seal	1	\$ 50.00
3	Tailgate outer garnish clips	1set	\$ 50.00

4	Tailgate inner trim board clips	1set	\$	60.00
5	End panel inner garnish clips	1set	\$	50.00
6	End panel joint sealant	1	\$	70.00
7	Rear bumper reverse sensor	1set	\$	320.00
8	Rear bumper clips	1set	\$	60.00
9	Rear bumper RH splash shield clips	1set	\$	40.00
10	Rear bumper LH splash shield clips	1set	\$	40.00
11	Rear fender RH inner trim board clips	1set	\$	60.00
12	Rear fender LH inner trim board clips	1set	\$	60.00
13	Rear fender RH joint sealant	1	\$	70.00
14	Rear fender RH glass inner seal	1	\$	50.00
15	Rear fender RH glass inner seal	1	\$	25.00
16	RH taillamp panel joint sealant	1	\$	30.00
17	Rear number plate	1	\$	70.00

SPECIAL NETT TOTAL : \$ 1,185.00

NO.	LABOUR CHARGES	AMOUNT
1	Cut/Weld, panel beating, straighten and alignment affected parts and areas. To remove, replace and check items	\$ 1,300.00 800
2	Putty, sand down and re-spray affected areas and parts on the affected areas	\$ 1,200.00 800
3	Check and test wiring system and lighting system	\$ 70.00 30
4	Apply anti-rust coating on replaced and repaired parts and areas	\$ 80.00 60
5	Remove and reinstall tailgate windscreen glass and sealants to assist repair	\$ 200.00 120
6	Remove and reinstall tailgate inner mechanism to new tailgate	\$ 120.00 60
7	Remove and replace tailgate reverse camera to assist repair	\$ 80.00 40
8	Remove and replace rear inner trims, garnish and boards to assist repair	\$ 250.00 60
9	Remove and replace rear bumper reverse sensors to assist repair	\$ 80.00 40
10	Remove and replace exhaust silencer and gasket to assist repair	\$ 180.00 60

LABOUR TOTAL : \$ 3,560.00

LIST PRICE: \$ 5,021.84
 SPECIAL NETT: \$ 1,185.00
 LABOUR: \$ 3,560.00
 TOTAL: \$ 9,766.84

5 Days

Lumpsum Repair

After repair photos.

Guo Qiang

8288 0282

21/11/22