



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22011623/Uqy3m4 Date: 28/02/2023 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SNC 2873C	Veh. Inspected	SKR 4716S	
Policy No.		Coverage (\$)	0.00	
Claim No.	DVS22/0125	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	17/11/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HARRIER (A)	c.c	1986	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	ZSU600033978	Colour	PEARL WHITE	
Odometer	114392 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/55 R18	PETLAS	6 mm	
L/H Front Tyre	235/55 R18	PETLAS	6 mm	
R/H Rear Tyre	235/55 R18	PETLAS	6 mm	
L/H Rear Tyre	235/55 R18	PETLAS	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	14/11/2022	Inspection Date	18/11/2022	
Survey held at	ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130			
<b>5a. Remarks</b>				
A)REGISTRATION DATE: 10 FEB 2015 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	