



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MAH LIAN MOTOR VEHICLE REPAIRER		Ref:	CS/TP22011628/Uvy3m4
38 DEFU LANE 9 SINGAPORE 539278		Date:	01/12/2022
ON BEHALF OF GOH LIANG TIEK		Code:	TP150
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.		Veh. Inspected	SBW 7878T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/11/2022
2. Vehicle Particulars & Condition			
Make & Model	BMW X6 XDRIVE (A)	c.c	2998
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	WBACY620909F77451	Colour	BLUE
Odometer	29001 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/40 R21	HANKOOK	6 mm
L/H Front Tyre	275/40 R21	HANKOOK	6 mm
R/H Rear Tyre	315/35 R21	HANKOOK	6 mm
L/H Rear Tyre	315/35 R21	HANKOOK	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/10/2022	Inspection Date	18/11/2022
Survey held at	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	