



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22011629/Uny3e2 Date: 09/01/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLK 7026E	Veh. Inspected	SKU 8275E	
Policy No.	D22MTPV01012497	Coverage (\$)	0.00	
Claim No.	CMTD2204190/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	18/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 SP (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JM6BK106280368393	Colour	MAROON	
Odometer	195535 KM	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	KUMHO	6 mm	
L/H Front Tyre	205/55 R16	KUMHO	6 mm	
R/H Rear Tyre	205/55 R16	FALKEN	6 mm	
L/H Rear Tyre	205/55 R16	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/11/2022	Inspection Date	18/11/2022	
Survey held at	ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	