




EQBH PLE LTD®

REGISTRATION NO: 201709306E

25 Kaki Bukit Road 4

Synergy@KB #03-79 Singapore (417800)

Contact: 63846939 / 90113391

Email: equator.brotherhood@gmail.com

PRE - REPAIR INSPECTION

Bike Model: Yamaha Nmax 155 V2

Bike Plate: FBT9810R

S/N	Parts Description	Quantity	Unit Price	Amount
1	Yamaha front suspension <i>X Local Repair</i>	2	\$ 300.00	\$ 600.00
2	Yamaha triple clamp (bottom) <i>X</i>	1	\$ 200.00	\$ 200.00
3	Yamaha steering cone <i>X</i>	1	\$ 110.00	\$ 110.00
4	Yamaha front rim <i>X</i>	1	\$ 360.00	\$ 360.00
5	Yamaha front wheel shaft <i>X</i>	1	\$ 45.00	\$ 45.00
6	Yamaha front wheel bearing <i>X</i>	2	\$ 35.00	\$ 70.00
7	Yamaha front wheel seal <i>X</i>	2	\$ 15.00	\$ 30.00
8	Yamaha front wheel bush <i>X</i>	2	\$ 30.00	\$ 60.00
9	Yamaha front wheel shaft center bush <i>X NN</i>	1	\$ 20.00	\$ 20.00
10	Yamaha rear brake lever (left) <i>X</i>	1	\$ 35.00	\$ 35.00
11	Yamaha rear brake lever holder (left) <i>X</i>	1	\$ 45.00	\$ 45.00
12	Yamaha rear brake lever cable (left) <i>X</i>	1	\$ 45.00	\$ 45.00
13	Yamaha front brake caliper <i>X</i>	1	\$ 180.00	\$ 180.00
14	Yamaha front brake pad <i>X</i>	1	\$ 35.00	\$ 35.00
15	Yamaha front brake disc <i>X</i>	1	\$ 110.00	\$ 110.00
16	Yamaha front signal light <i>X</i>	1	\$ 60.00	\$ 60.00
17	Yamaha front mudguard (silver) <i>Scr /</i>	1	\$ 75.00	\$ 75.00
18	Yamaha front mudguard holder (matte black) <i>X NN</i>	1	\$ 55.00	\$ 55.00
19	Yamaha floorboard (matte black) <i>X NN</i>	2	\$ 60.00	\$ 120.00
20	Yamaha floorboard cover (silver) <i>X NN</i>	1	\$ 65.00	\$ 65.00
21	Yamaha side fairing 1 <i>X NN</i>	1	\$ 55.00	\$ 55.00
22	Yamaha side fairing 2 <i>X NN</i>	1	\$ 60.00	\$ 60.00
23	Yamaha tail fairing (silver) <i>Scr /</i>	1	\$ 65.00	\$ 65.00
24	Yamaha headlight <i>X NN</i>	1	\$ 380.00	\$ 380.00
25	Yamaha handle bar <i>X NN</i>	1	\$ 95.00	\$ 95.00

EQBH PLE LTD®

REGISTRATION NO: 201709306E



EQBH PLE LTD®

REGISTRATION NO:201709306E

25 Kaki Bukit Road 4

Synergy@KB #03-79 Singapore (417800)

Contact: 63846939 / 90113391

Email: equator.brotherhood@gmail.com

PRE - REPAIR INSPECTION

Bike Model: Yamaha Nmax 155 V2

Bike Plate: FBT9810R

S/N	Parts Description	Quantity	Unit Price	Amount
26	Yamaha front windshield X NN	1	\$ 45.00	\$ 45.00 x
27	Motul brake fluid X NN	1	\$ 15.00	\$ 15.00 x
28	Front number plate Pent /	1	\$ 15.00	\$ 15.00 -
29	Playlife grip X NN	1	\$ 35.00	\$ 35.00 x
30	Alignment (chassis) X NN	1	\$ 580.00	\$ 580.00 x
31	Towing 1-trip (Reporting Center to workshop)	1	\$ 80.00	\$ 80.00 30
32	Towing 1-trip (Workshop to Reporting Center)	1	\$ 80.00	\$ 80.00 30 } 60
33	Towing 1-trip (TP to workshop)	1	\$ 80.00	\$ 80.00 X NN
34	Labor (\$280)	1	\$ 480.00	\$ 480.00
35				\$ -
36				\$ -
37				\$ -
38				\$ -
39				\$ -
40				\$ -
41				\$ -
42				\$ -
43				\$ -
44				\$ -
45				\$ -
46				\$ -
47				\$ -
48				\$ -
49				\$ -
50				\$ -
51				\$ -

Handwritten calculations:
Total parts = 1440
10% = 144
Total = 1584
20% = 316.8
Total = 1800.8
Total = 479
20% = 95.80
= 383.20
= 400.00

44 LKK Auto Consultants hence notify
45 the Repairer of the following:
46 • To resurvey before/after spray painting
47 • To display damaged part(s) during resurvey
48 • Parts prices are subject to confirmation
49 • Third party survey is on a "Without Prejudice" basis
50 • No illegal modification(s) is allowed
51 • Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company
51 Acknowledged by Repairer
Signature:
Date:

EQBH PLE LTD®
REGISTRATION NO:201709306E