



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Xiao Chen.

Date: 18/11/2022

Attn: The Motor Claims Department
Your Insured Vehicle - SHD 6338 X

First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877
Tel : 6507 3848
Fax : 6507 3849

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

Estimated Cost of repair for Vehicle Mitsubishi Outlander SKV 2795 E & SHD 6338 X ON 11/11/2022 at 22:30pm.

1pc	Rear Boot Cover	Dented	2492	\$ 984.00	Nett ✓
1pc	Rear Boot Logo	Abc me		\$ 101.00	Nett +
1pc	Rear Boot Outlander Plate	me	2242.80	\$ 121.00	Nett ✓
1pc	Rear Boot Mivec Plate	me		\$ 91.00	Nett ✓
1pc	Rear Bumper	Dented		\$ 807.00	Nett ✓
2pcs	Rear Bumper Side Retainer	me	2pcs x \$78.00	\$ 156.00	Nett +
1pc	Rear Bumper Spoiler	Dented		\$ 489.00	Nett ✓
				\$ 2,749.00	
Less 25%				-\$ 687.25	
				\$ 2,061.75	
1pc	Reverse Sensor	Damaged	280	\$ 428.00	S/Nett 200
1pc	Rear Windscreen Glass Seal	me		\$ 98.00	S/Nett 40
1pc	Windscreen Glass Sealant			\$ 80.00	S/Nett 40

To dismantl & replace damage parts, panel beat where necessary

To putty, apply primer & spray paint on the affected portion.

To dismantl & refix rear windscreen glass

To check wiring functions.

\$ 780.00 - 500

\$ 780.00 - 400

\$ 180.00 - 120

\$ 120.00 - 30

\$ 4,527.75

blnd: 3572.80 Adrian Y
L/S: 2.81K 2/5 21/11/22
04 days