

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Adress : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

OD CLAIM

To : Lonpac Insurance Bhd
Motor Claims Dept

Date : 18 Nov 2022

Dear Sirs :

Fax : 6896 8706

RE : ESTIMATE COST FOR MITSUBIAHI FM65F - YN3148T
ALONG BUKIT BATOK ROAD (LAMO POST 87 ON 04/11/2022

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Front bumper	1pc	\$ 950.00 ⁶⁷ 300
2	Front side bumper @\$300ea	2pcs	\$ 440 600.00 ^{RH-61}
3	Front bumper lower	1pc	\$ ⁿⁿ 450.00 ⁷⁸⁰
4	Front headlamp @\$780ea	2pcs	\$ 440 1,560.00 ^{RH-61}
5	Front center grille	1pc	\$ 790.00 ^{eng}
6	Emblem	1pc	\$ 280.00 ^{ea} 160
7	Front panel	1pc	\$ 2,300.00 ^{eng} 2000
8	Fuso	1pc	\$ 230.00 ^{eng}
9	Front corner panel rh	1pc	\$ 1,050.00 ^{dis} 805
10	Front corner panel lamp rh	1pc	\$ 250.00 ^{eng}
11	Front windscreen glass	1pc	\$ 1,650.00 ^{eng} 1500
12	Front windscreen rubber	1pc	\$ 350.00 ^{eng} 280
13	Front door rh	1pc	\$ 4,999.00 ^{XR}
14	Front door lock/ actuator rh	1pc	\$ 850.00 ^{XR}
15	Front door hinge @\$360earh	2pcs	\$ 720.00 ^{Rp}
16	Front step panel rh	1pc	\$ 220.00 ^{eng}
17	Front wheel mudguard rh	1pc	\$ 250.00 ^{eng}
			\$ 17,499.00
Add 15%			\$ 2,624.85 ⁸⁹⁶⁰
Sum Carried Forward			\$ 20,123.85 ¹⁰³⁰⁴

Sum Carried Forward**\$ 20,123.85**

- 18 Front ERP bracket
19 Front number plate

1pc \$ 15.00 *na*
1pc \$ 25.00 *bf*

40

Labour Charge & Misc

To remove, repair, replace & install front damaged parts.

} \$ 1,200.00 *900*
}

To R & R front windscreen glass

\$ 150.00 ✓

To remove & install door mechanism & check for function

} \$ 180.00 *x na*
}

To company logo "Teng Leng Industries"

\$ 250.00 *180*

To R & R wiring

\$ 60.00 *30*

To putty & spray painting.

\$ 1,500.00 *1000*

Total

\$ 23,503.85 *2260*

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

Tan Jui 97495749
Not Authorised 18/11/22 350pm
Exp: fb9
L/S Resurvey after repair
tanjui@lkh.com.hk

7 days
10304
40
2260
12604
45910,050
7 days
9504.75
40
2260
11804.75
45910,050
7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date: