

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

18-Nov-22

## ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1465 U

1 pc	Front bumper	✓	\$	811.11
1 pc	Front bumper reinforcement	X X SNN	\$	636.40
1 pc	Front bumper sponge	X X SNN	\$	218.03
1 pc	Front n/s head lamp	✓ Aut	\$	1,531.57
1 2 pcs	Front bumper n/s & o/s side bracket @ \$32.51	✓ <del>42.51</del>	\$	65.02
1 pc	Front n/s fender	✓ BUC.	\$	514.02
1 pc	Front n/s fender inner shield	?	\$	176.72
1 pc	Front n/s fender signal lamp	X SNN	\$	32.10
1 pc	Front n/s mud flap	X	\$	47.45
1 pc	Front n/s rim	✓ BT.	\$	246.00
1 pc	Front n/s lower arm	1	\$	811.34
1 pc	Front n/s shock absorber	?	\$	611.56
1 pc	Front n/s tie rod end	?	\$	72.50
1 pc	Front n/s ball joint	?	\$	91.90
1 pc	Front n/s knuckle arm	?	\$	873.88
1 pc	Front n/s knuckle bearing	?	\$	349.60
1 pc	Front n/s stabilizer link	?	\$	88.50
1 pc	n/s mirror assy	X Rep	\$	742.49
				\$ 7,920.19
Less 20%				\$ 1,584.04
				\$ 6,336.15

### S/NETT

1 set	Front bumper clips	✓	\$	48.00
1 set	Front n/s fender inner shield clips	✓ GABC.	\$	28.00
1 pc	Front n/s fender sticker	✓	\$	30.00
1 pc	'15" Tyre (Tyre Brand: Maxxis)	X NNV	\$	250.00

18-Nov-22

**ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1465 U**

Sundry	\$	50.00	X NN
Towing Fee	\$	50.00	/
To check front n/s wheel alignment	\$	80.00	60
To dismantle / refit front n/s undercarriage	\$	250.00	?
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	X NN
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the front bumper, front n/s fender, n/s side mirror, support panel, etc	\$	1,000.00	400
To putty and spray painting on the front bumper, front n/s fender, n/s side mirror	\$	600.00	450 <del>650</del>
To apply rustproofing on repaired/replaced panel	\$	80.00	60
<b>Total</b>	<b>\$</b>	<b>8,982.15</b>	

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

5 Days.

4/5

After mprc pths.

Gmz Qry

21/11

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 ( 3 LINES ) FAX : 6743 0013

Email: peoplevehicle@gmail.com

Reg No: 200415052W



Date: 16/11/22

CASH SALE/WORK ORDER No: PE 6543

寶號

Messrs: P AUTO (PIT)

車號

Vehicle No: SHD14650

車型

Model No: I30

由

From: 2/ JIN TENTERAM

到

To: OMEGA LEVEL 1

其他

Remark: 94887249

時間

Time: 22:50-23:10-23:40

AMOUNT: \$ 50

- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ Jump Start
- ☐ Changing of Battery
- ☐ Tyre Replacement/ Patching
- ☐ Crane Up/Winch Out
- ☐ With Load/Cargo Box
- ☐ Flat Bed
- ☐ King Dolly to lift up
- ☐ Low Body Kit
- ☐ Repo
- ☐ Door Opening Service
- ☐ Collect Document/Key
- ☐ Jurong Island/Cargo Complex
- ☐ Woodlands/Tuas Checkpoint
- ☐ Cancellation Charge (Reach Location)
- ☐ Cancellation Charge (After 15 minutes)

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by: [Signature] YN3901

收貨人

Received by: [Signature]