

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

18-Nov-22

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1465 U

1 pc	Front bumper / <i>ll</i>	\$	811.11 ✓
1 pc	Front bumper reinforcement X	\$	636.40
1 pc	Front bumper sponge X	\$	218.03
1 pc	Front n/s head lamp / <i>Ant</i>	\$	1,531.57 ✓
2 pcs	Front bumper n/s & o/s side bracket @ \$32.51 <i>4pc LH</i>	\$	65.02 <i>32.51</i>
1 pc	Front n/s fender / <i>Buc.</i>	\$	514.02 ✓
1 pc	Front n/s fender inner shield ?	\$	176.72
1 pc	Front n/s fender signal lamp X	\$	32.10
1 pc	Front n/s mud flap X	\$	47.45
1 pc	Front n/s rim / <i>BT.</i>	\$	246.00 ✓
1 pc	Front n/s lower arm 1	\$	811.34 ✓
1 pc	Front n/s shock absorber ?	\$	611.56 ✓
1 pc	Front n/s tie rod end ?	\$	72.50 ✓
1 pc	Front n/s ball joint ?	\$	91.90
1 pc	Front n/s knuckle arm ?	\$	873.88 ✓
1 pc	Front n/s knuckle bearing ?	\$	349.60 ✓
1 pc	Front n/s stabilizer link ?	\$	88.50 ✓
1 pc	n/s mirror assy X <i>Repair</i>	\$	742.49
		\$	7,920.19
		Less 20%	\$ 1,584.04
		\$	6,336.15

5942.59
-20%
4754.07

S/NETT

1 set	Front bumper clips /	\$	48.00
1 set	Front n/s fender inner shield clips / <i>LMBC.</i>	\$	28.00
1 pc	Front n/s fender sticker ✓	\$	30.00
1 pc	'15" Tyre (Tyre Brand: Maxxis) X	\$	250.00

106

18-Nov-22

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1465 U

Sundry	\$	50.00	X
Towing Fee	\$	50.00	/
To check front n/s wheel alignment	\$	80.00	60.
To dismantle / refit front n/s undercarriage	\$	250.00	7150?
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	X
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the front bumper, front n/s fender, n/s side mirror, support panel, etc	\$	1,000.00	400
To putty and spray painting on the front bumper, front n/s fender, n/s side mirror	\$	600.00	450
To apply rustproofing on repaired/replaced panel	\$	80.00	60.
Total	\$	<u>8,982.15</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

5 Days.

4/5

After repair pmtg.

Gms Qirp

26/11

Before

Work Order ID

SHD1465U

PREMEIR AUTOMOTIVE SERVICE PTE LTD

Date

2022-November-25 06:47p.m.

Hyundai : i30/Elantra Neos : 2012-18 (GDe) Independent Rear Suspension : T-GDI

Left Front					Right Front			
Actual	Before	Specified Range			Actual	Before	Specified Range	
-0°53'	-0°53'	-1°00'	0°00'	Camber	-0°17'	-0°17'	-1°00'	0°00'
.		4°42'	5°42'	Caster			4°42'	5°42'
-0°14'	-0°14'	-0°01'	0°11'	Toe	0°01'	0°01'	-0°01'	0°11'
.		13°18'	14°18'	SAI			13°18'	14°18'
.		12°18'	14°18'	Included Angle			12°18'	14°18'
.				Turning Angle Diff.				

Front			
	Actual	Before	Specified Range
Cross Camber	-0°36'	-0°36'	
Cross Caster			
Total Toe	-0°13'	-0°13'	-0°02' 0°22'

Left Rear				Camber Toe	Right Rear			
Actual	Before	Specified Range			Actual	Before	Specified Range	
-1°07'	-1°07'	-1°30'	-0°30'		-0°55'	-0°55'	-1°30'	-0°30'
0°00'	0°00'	-0°04'	0°08'	0°05'	0°05'	-0°04'	0°08'	

Rear			
	Actual	Before	Specified Range
Total Toe	0°05'	0°05'	-0°08' 0°16'
Thrust Angle	-0°03'	-0°03'	