

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

18-Nov-22

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1465 U

1 pc	Front bumper	✓	\$	811.11	✓
1 pc	Front bumper reinforcement	X X } nn	\$	636.40	
1 pc	Front bumper sponge	X X } nn	\$	218.03	
1 pc	Front n/s head lamp	✓	\$	1,531.57	✓
1 2 pcs	Front bumper n/s & o/s side bracket @ \$32.51	✓ 4 pc BR	\$	65.02	32.51 ✓
1 pc	Front n/s fender	✓	\$	514.02	✓
1 pc	Front n/s fender inner shield	? X nn	\$	176.72	
1 pc	Front n/s fender signal lamp	X } nn	\$	32.10	
1 pc	Front n/s mud flap	X nn	\$	47.45	
1 pc	Front n/s rim	✓	\$	246.00	✓
1 pc	Front n/s lower arm	1 BT	\$	811.34	✓
1 pc	Front n/s shock absorber	? BT	\$	611.56	✓
1 pc	Front n/s tie rod end	? BT	\$	72.50	✓
1 pc	Front n/s ball joint	? X nn	\$	91.90	
1 pc	Front n/s knuckle arm	? BT	\$	873.88	✓
1 pc	Front n/s knuckle bearing	? NEC	\$	349.60	✓
1 pc	Front n/s stabilizer link	? BT	\$	88.50	✓
1 pc	n/s mirror assy	X Repir	\$	742.49	
			\$	7,920.19	
			\$	1,584.04	
			\$	6,336.15	

5942.59
-20%
4754.07

Less 20%

S/NETT

1 set	Front bumper clips	✓	\$	48.00	30 ✓
1 set	Front n/s fender inner shield clips	✓	\$	28.00	20 ✓
1 pc	Front n/s fender sticker	✓	\$	30.00	25 ✓
1 pc	'15" Tyre (Tyre Brand: Maxxis)	X nn	\$	250.00	

18-Nov-22

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1465 U

Sundry	\$	50.00	X NN
Towing Fee	\$	50.00	/
To check front n/s wheel alignment	\$	80.00	60.
To dismantle / refit front n/s undercarriage	\$	250.00	? 150
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	X NN
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the front bumper, front n/s fender, n/s side mirror, support panel, etc	\$	1,000.00	400
To putty and spray painting on the front bumper, front n/s fender, n/s side mirror	\$	600.00	450 650
To apply rustproofing on repaired/replaced panel	\$	80.00	60.
	\$	8,982.15	

Total

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

5999.07

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

L/S - 4799.25
= 4800

5 Days.
4/5
After myri plots.
Gms Ring
21/11

L&K Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Email: peoplevehicle@gmail.com

Reg No: 200415052W



Date: 16/11/22

CASH SALE/WORK ORDER No: PE 6543

寶號

Messrs:

P AUTO (PIT)

車號

Vehicle No:

SHD14650

車型

Model No:

I30

由

From:

2/ JIN TENTERAM

到

To:

OMEGA LEVEL 1

其他

Remark:

94887249

時間

Time:

22:50-23:10-23:40

AMOUNT: \$

50

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by:

YN3901

收貨人

Received by:

[Signature]

- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ Jump Start
- ☐ Changing of Battery
- ☐ Tyre Replacement/ Patching
- ☐ Crane Up/Winch Out
- ☐ With Load/Cargo Box
- ☐ Flat Bed
- ☐ King Dolly to lift up
- ☐ Low Body Kit
- ☐ Repo
- ☐ Door Opening Service
- ☐ Collect Document/Key
- ☐ Jurong Island/Cargo Complex
- ☐ Woodlands/Tuas Checkpoint
- ☐ Cancellation Charge (Reach Location)
- ☐ Cancellation Charge (After 15 minutes)