

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 65441510
CO. REG: 200707743D GST REG: 200707743D

LKK Auto Consultants hence notify the Insurer of the following:
No resurvey before/after spray painting
No resurvey during resurvey
Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

21-Nov-22

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1099 T

Acknowledged by Repairer
Signature:
Date:

1 pc	Front bumper / <i>re</i>		\$ 531.00
1 pc	Front bumper emblem / <i>abc</i>		\$ 44.00
2 pcs	Front bumper o/s & o/s side retainer @ \$16.00	<i>X</i> <i>nn</i>	\$ 32.00
1 pc	Front bumper o/s fog light cover	<i>X</i>	\$ 66.00
1 pc	Front bumper o/s protector	<i>X</i>	\$ 51.00
1 pc	Front o/s fender / <i>lme</i>		\$ 384.00
1 pc	Front o/s fender inner shield / <i>le</i>		\$ 120.00
1 pc	Front o/s headlamp ? <i>x nn</i>		\$ 1,028.00
			<hr/> \$ 2,256.00
		Less 10%	\$ 225.60
			<hr/> \$ 2,030.40

S/NETT

1 set	Front bumper clips / <i>nn</i>		\$ 48.00
1 pc	Front o/s fender sticker / <i>nn</i>		\$ 30.00
1 set	Front o/s fender inner shield clips / <i>nn</i>		\$ 28.00
	Sundry		\$ 50.00 <i>X</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 180.00 <i>X</i> <i>San</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc		\$ 650.00 <i>400</i>
	To putty and spray painting on front bumper, front o/s fender		\$ 400.00 <i>/</i>
	To apply rustproofing on the repaired and replaced panels.		\$ 80.00 <i>60</i>
			<hr/> \$ 3,496.40

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

*2 Days.
L/S After repair photos.
Caro King. 21/11/22.*