

PM2B200S003260869.

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

TP Budget Direct.

Yiao Chuan.

## ESTIMATE

Vehicle No : SLR4527J

Make/Model : PERODUA AXIA

Chassis No: PM2B200S003260869

Accident date : 16.11.2022

No	DESCRIPTION	Qty	Amount (\$S)
<b>List Items</b>			
1	Rear bumper <i>Deland</i>	1	\$ 485.
2	Rear bumper side holder <i>new</i>	1	\$ 28
3	Rear bumper lip <i>Deland</i>	1	\$ 390.
4	Rear bumper RH lower cover <i>cut</i>	1	\$ 75
5	Rear end panel <i>new</i>	1	\$ 432
6	Rear RH lamp <i>cut</i>	1	\$ 298.
7	Rear number plate seal <del>X</del> NN	1	\$ 20.
			\$
		Less 10% Disc	\$
		<b>Total</b>	\$

1248  
1123.20

<b>Special Nett Items</b>			
1	Rear bumper reverse sensor <i>Deland</i>	2	\$ 380.00
2	Rear bumper clips (1 set) <i>new</i>	1	\$ 50.00
3	Rear camera <i>new</i>	1	\$ 500.00
4	Rear number plate <i>new</i>	1	\$ 50.00
5	Rear number plate holder <i>new</i>	1	\$ 50.00
		<b>Total</b>	\$ 1,030.00

260

<b>Labour Cost</b>			
1	Remove & reinstall number seal		\$ 80
2	Remove, replace & repair consistent to the accident		\$ 800.00
3	Respray painting		\$ 800.00
		<b>Total</b>	\$

860

**Grand Total**

\$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

total: 2243.20

H/S: 1.8k

03 Days

1.8k