

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIS22011649/UPA3Q2**Date:** 16/03/2023**REFERENCE**

|                              |                                       |                             |                 |
|------------------------------|---------------------------------------|-----------------------------|-----------------|
| Handling Insurer:            | Allianz Insurance Singapore Pte. Ltd. | Policy No:                  | SP2000443531-01 |
| <b>Claimant Vehicle No :</b> | SJT3345L                              | <b>Insured Vehicle No :</b> | SMU8429E        |
| Date of Loss:                | 17/11/2022                            | Nature of Claim:            | TP              |
|                              |                                       | Claim No:                   | N/A             |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                    |
|-----------------------------|-----------------------------------|-------------|--------------------|
| Reg No:                     | <b>SJT3345L</b>                   | Engine No:  | G4FC9U681169       |
| Make & Model:               | HYUNDAI HD AVANTE, 1.6 (A)        | Chassis No: | KMH DU41BR9U802445 |
| Reg. Date:                  | 02/10/2009 (Man. Year: 2009)      | Odometer:   | 132952 km          |
| Colour:                     | Black                             |             |                    |
| Engine Capacity:            | 1591 cc                           |             |                    |
| Market Value/New Car Price: | N/A                               |             |                    |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                    |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 185/65 R15    | Rear Tyre Size:  | 185/65 R15    |
| Front Left Side:  | Yokohama 6 mm | Rear Left Side:  | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts   | 5,990.92          | 3,320.16          | 2,670.76          | 44.58         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour  | 3,120.00          | 1,790.00          | 1,330.00          | 42.63         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing  | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>9,110.92</b>   | <b>5,110.16</b>   | <b>4,000.76</b>   | <b>43.91</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>3,500.00</b>   |                   |               |
| <b>Nett Amount (S\$)</b>                        | <b>9,110.92</b>   | <b>3,500.00</b>   | <b>5,610.92</b>   | <b>61.58</b>  |
| <b>+ Loss of Use (5.0 x S\$50.00/day) (S\$)</b> |                   | 250.00            |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>3,750.00</b>   |                   |               |

**INSPECTION**

|                             |                          |  |
|-----------------------------|--------------------------|--|
| Date of Assignment:         | 18/11/2022               | Nineteen Autowerks Pte Ltd (HQ)                    |
| Date Inspected:             | 18/11/2022 Inspected At: | BLK 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE |
| Estimated Period of Repair: | 5.0 days                 | Singapore 417808                                   |

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |  |   |
|---------------|--|---|
| Reference     |  |   |
| Part Source:  | MRM-SG   | Version: 1.0 (Last Synchronised: 15 Mar 2023)               |
| Parts:        | 143  | HYUNDAI HD AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's   | (Price-denominated Standard List)                           |
| Print Code:   | (Unsubmitted, no print-code for SJT3345L)  |   |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.   |   |

Recommended Parts

| No. | Qty | Part No. | Particulars                      | Condition     | Repairer's  | Amount            |
|-----|-----|----------|----------------------------------|---------------|---|-------------------|
| 1   | 1   |          | *FRONT BUMPER                    | Distorted     | 980.20 FL   | *494.40 FL        |
| 2   | 1   |          | *FRONT BUMPER SIDE RETAINER      | O/S Cracked   | 196.80 FL   | *65.00 FL         |
| 3   | 1   |          | *FRONT BUMPER CENTRE GRILLE      | Twisted       | 196.20 FL   | *102.30 FL        |
| 4   | 1   |          | *HEADLAMP (RH)                   | Cracked       | 1,655.50 FL   | *850.00 FL        |
| 5   | 1   |          | *HEADLAMP LOWER BRACKET (RH)     | Cracked       | 172.60 FL   | *88.50 FL         |
| 6   | 1   |          | *FRONT FENDER (RH)               | Badly Dented  | 845.20 FL   | *845.20 FL        |
| 7   | 1   |          | *FRONT FENDER INNER SHIELD (RH)  | Torn          | 195.80 FL   | *189.30 FL        |
| 8   | 1   |          | *FRONT BUMPER REINFORCEMENT      | Distorted     | 396.50 FL   | *316.00 FL        |
| 9   | 1   |          | *FRONT BUMPER SPONGE             | Torn          | 387.40 FL   | *102.30 FL        |
| 10  | 1   |          | *FRONT WASHER TANK               | Deformed      | 104.00 FL   | *104.00 FL        |
| 11  | 1   |          | *FRONT SUPPORT PANEL             | Cracked       | 418.20 FL   | *418.20 FL        |
| 12  | 1   |          | *FRONT CHASSIS MEMBER            | Repair        | 296.50 FL   | *- FL             |
| 13  | 1   |          | *SUNDRIES                        | Not Necessary | 60.00 FS  | *- FS             |
| 14  | 1   |          | *FRONT BUMPER CLIPS              | Necessary     | 100.00 FS   | *40.00 FS         |
| 15  | 1   |          | *FRONT FENDER INNER SHIELD CLIPS | Necessary     | 55.00 FS  | *40.00 FS         |
| 16  | 1   |          | *FRONT RIM (RH)                  | Warped        | 850.00 FS   | *380.00 FS        |
| 17  | 1   |          | *FRONT TYRE (RH)                 | Serviceable   | 250.00 FS   | *- FS             |
|     |     |          |                                  |               | Sub Total (\$\$)                                    | 7,159.90 4,035.20 |
|     |     |          |                                  |               | - List Item Discount on L Items 20.00/20.00% (\$\$) | 1,168.98 715.04   |
|     |     |          |                                  |               | Total Parts (\$\$)                                  | 5,990.92 3,320.16 |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                             | Particulars                                    | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--|----------|-----------------|-----------------|
| <b>Labour Items</b>            |  |          |                 |                 |
| 1                              | PANEL BEATING                                  | New      | 1,400.00        | 900.00          |
| 2                              | SPRAY PAINTING                                 | New      | 1,200.00        | 800.00          |
| 3                              | TO CONDUCT COMPUTERISE WHEEL ALIGNMENT         | New      | 120.00          | 60.00           |
| 4                              | TO REMOVE & REFIT FRONT UNDERCARRIAGE          | New      | 200.00          | 0.00            |
| 5                              | CHECK WIRING SYSTEM AFTER DISCONNECT & CONNECT | New      | 100.00          | 0.00            |
| 6                              | TO APPLY UNDERCOATING FOR RUST PROOFING        | New      | 100.00          | 30.00           |
| <b>Gross Labour Cost (S\$)</b> |  |          | <b>3,120.00</b> | <b>1,790.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >