

(08/11/13) wef

ASS. REC. BY: *marcus*

REF: *CC4/ A1522011649/423*

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

NINETEEN AUTOWERKS PTE LTD

Blk 436 Tampines Street 43

#07-97 Singapore 520436

Tel: (65) 9674 1991

✉ nineteenautowerks@gmail.com

not Arthur
all
morning
18/11/22
1/5 @ 4000/
5 days



NINETEEN
AUTOWERKS

ESTIMATE

DATE: 18-Nov-22

DOA: 17-Nov-22

VEHICLE NO: SJT 3345 L

MAKE & MODEL: Hyundai Avante

DESCRIPTION	QUANTITY	AMOUNT	TOTAL
LIST ITEMS			
Front bumper	1	\$980.20	494.40 715 \$980.20 ✓
Front bumper side retainer	2	\$98.40	65.00 1/5 cm \$196.80 120
Front bumper centre grille	1	\$196.20	102.30 7w1 \$196.20 —
Headlamp (RH)	1	\$1,655.50	850 one \$1,655.50 —
Headlamp lower bracket (RH)	1	\$172.60	88.50 cm \$172.60 —
Front fender (RH)	1	\$845.20	1.5 cm \$845.20 —
Front fender inner shield (RH)	1	\$195.80	189.30 7w1 \$195.80 —
Front bumper reinforced	1	\$396.50	316.00 715 \$396.50 ✓
Front bumper sponge	1	\$387.40	102.30 7w1 \$387.40 —
Front washer tank	1	\$104.00	20 \$104.00 —
Front support panel	1	\$418.20	one \$418.20 —
Front chassis member	1	\$296.50	2 \$296.50 X
		Total	\$5,844.90
		Less 20%	\$1,168.98
			\$4,675.92

SPECIAL NETT ITEMS

Sundries	1	\$60.00	\$60.00 X
Front bumper clips	1	\$100.00	\$100.00 40
Front fender inner shield clips	1	\$55.00	\$55.00 40
Front Rim (RH)	1	\$850.00	\$850.00 380
Front tyre (RH)	1	\$250.00	\$250.00 X
			\$1,315.00
	Parts Total		\$5,990.92

LABOUR CHARGES

Panel beating	\$1,400.00	900
Spray painting	\$1,200.00	800
To conduct computerise wheel alignment	\$120.00	60
To remove & refit front undercarriage	\$200.00	X
Check wiring system after disconnect & connect	\$100.00	X
To apply undercoating for rust roofing	\$100.00	30
	\$3,120.00	

Total Parts and Labour Cost of Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3575.20
202
2860.16
460