

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22011650/APA3Q2**Date:** 03/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700033196-05
Claimant Vehicle No :	SMZ6527S	Insured Vehicle No :	GBG2955X
Date of Loss:	10/11/2022	Nature of Claim:	TP
		Claim No:	6079239458SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ6527S	Engine No:	1KR2570632
Make & Model:	TOYOTA RAIZE, 1.0 X CVT (A)	Chassis No:	A200A0014050
Reg. Date:	10/05/2021 (Man. Year: 2020)	Odometer:	69056 km
Colour:	Black		
Engine Capacity:	996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R16	Rear Tyre Size:	195/65 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,005.44	2,491.24	3,514.20	58.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	1,470.00	840.00	36.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,315.44	3,961.24	4,354.20	52.36
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	8,315.44	3,100.00	5,215.44	62.72
+ GST 8.00/8.00% (S\$)	665.24	248.00	417.24	62.72
Nett Amount (S\$)	8,980.68	3,348.00	5,632.68	62.72
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
Nett Liability (S\$)		3,648.00		

INSPECTION

Date of Assignment:	16/11/2022		
Date Inspected:	16/11/2022	Inspected At:	J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578 Singapore 539186
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,680.00 FL	*- FL
2	1		*TAILGATE LOCK	Not Necessary	427.00 FL	*- FL
3	1		*PAIZE EMBLEM	Necessary	49.56 FL	*49.56 FL
4	1		*LOGO EMBLEM	Necessary	72.20 FL	*72.20 FL
5	2		*TAILGATE REFLECTOR	Not Necessary	602.80 FL	*- FL
6	1		*TAILGATE W/STRIP	Cut	325.10 FL	*325.10 FL
7	2		*TAILLAMP	Not Necessary	1,348.00 FL	*- FL
8	1		*REAR BUMPER	Deformed	947.20 FL	*947.20 FL
9	1		*REAR BUMPER LOWER SPOILER	Deformed	353.40 FL	*353.40 FL
10	2		*REAR BUMPER REFLECTOR	Not Necessary	251.00 FL	*- FL
11	1		*REAR BUMPER GARNISH	N/S Torn	312.00 FL	*156.00 FL
12	2		*REVERSE SENSOR	Damaged	490.80 FL	*490.80 FL
13	2		*REAR BUMPER RETAINERS	Necessary	95.40 FL	*95.40 FL
14	1		*REAR BUMPER CLIPS (14 PCS)	Necessary	77.00 FL	*30.00 FL
15	1		*REAR NO PLATE LAMP	Not Necessary	173.80 FL	*- FL
16	1		*END PANEL	Dented	525.00 FL	*525.00 FL
17	1		*END PANEL INNER GARNISH	Deformed	157.00 FL	*157.00 FL
18	1		*REAR NO PLATE	Bent	40.00 FS	*40.00 FS
19	1		*REAR W/SCREEN GUM	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,977.26	3,291.66
- List Item Discount on L Items 25.00/25.00% (S\$)	1,971.82	800.42
Total Parts (S\$)	6,005.44	2,491.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING	New	1,000.00	600.00
3	WIRING	New	30.00	30.00
4	RUST PROOFING	New	80.00	60.00
5	REMOVE & REFIT REAR W/SCREEN	New	120.00	120.00
6	TRANSFER TAILGATE FITTINGS	New	80.00	60.00
Gross Labour Cost (S\$)			2,310.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >