

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 24 Mar 2023

Preliminary Advice

Vehicle No	: SNB8157C	Accident Date	: 16/11/2022
Make	: TESLA MODEL 3 PERFORMANCE	Policy No.	: SP2000621238-01
Assignment Date	: 19/11/2022	Excess	: S\$1,500.00
Date of Inspection	: 21/11/2022	Est. Duration of Repair	: 7
Inspection At	: OPTIMA WERKZ PTE LTD (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-05/06 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,121.95	(Estimate \$17,294.85 + Supplementary \$827.10)
Revised Amount	:S\$	14,586.98	(Inclusive of supplementary)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	14,586.98	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	234,000.00
COE / PARF Rebate	:S\$	95,145.00
Salvage Value	:S\$	
Margin for Repair	:S\$	138,855.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.