

Date : 18/11/2022
Vehicle No: SNB8157C
Model: TESLA MODEL 3 PERFORMANCE
Chassis: LRW3F7EL6MC283030 - 2021
Reg.Year: 2021
Policy No: SP2000621238-01
Date of Accident: 16/11/2022
Estimator: KIT

TO MOTOR CLAIM DEPT
ALLIANZ INSURANCE SINGAPORE
79 Robinson road, #09-01
Singapore 068897

*Not Authorized
Punery B & pain
7 days Ex \$1500k*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BONNET	1		<i>By</i> \$663.55	✓
2	FRONT BONNET "TESLA" EMBLEM	1		<i>na</i> \$48.60	✓
3	FRONT BONNET HINGE LH	1		<i>DIY</i> \$74.77	✓
4	FRONT BONNET HINGE RH	1		<i>DIY</i> \$74.77	✓
5	FRONT BONNET STRUT LH	1		\$52.34	?
6	FRONT BONNET STRUT RH	1		\$52.34	?
7	FRONT BONNET LOCK	1		<i>By</i> \$177.57	✓
8	FRONT BONNET LOCK ACTUATOR	1		<i>na</i> \$107.48	✓
9	FRONT BONNET LOCK STRIKER	1		<i>DIY</i> \$2.80	✓
10	FRONT LUGGAGE COMPARTMENT	1		<i>Reform</i> \$64.49	✓
11	FRONT LUGGAGE COMPARTMENT REINFORCEMENT	1		\$13.08	?
12	FRONT LUGGAGE COMPARTMENT BRACKET	1		\$2.40	?
13	FRONT LUGGAGE COMPARTMENT SEAL	1		<i>na</i> \$44.86	✓
14	FRONT WINDSCREEN GLASS	1		<i>CM</i> \$785.05	✓
15	FRONT HEADLAMP LH	1		<i>my CM</i> \$1,308.41	✓
16	FRONT HEADLAMP RH	1		<i>na</i> \$1,308.41	✓
17	FRONT HEADLAMP LOWER BRACKET LH	1		<i>CM</i> \$7.48	✓
18	FRONT HEADLAMP LOWER BRACKET RH	1		<i>CM</i> \$7.48	✓
19	FRONT HEADLAMP WIRE HARDNESS	1		\$88.79	?
20	FRONT BUMPER	1		<i>By</i> \$663.55	✓
21	FRONT BUMPER SIDE RETAINER LH	1		<i>DIY</i> \$1.87	✓
22	FRONT BUMPER SIDE RETAINER RH	1		<i>DIY</i> \$1.87	✓
23	FRONT BUMPER TOWING COVER	1		<i>su</i> \$14.95	X
24	FRONT BUMPER FOG LAMP LH	1		<i>su</i> \$271.03	X
25	FRONT BUMPER FOG LAMP RH	1		<i>su</i> \$271.03	X
26	FRONT BUMPER PARKING SENSOR	6	\$163.55	\$981.30	?
27	FRONT BUMPER PARKING SENSOR BRACKET	6	\$4.67	\$28.02	?
28	FRONT BUMPER SENSOR WIRE HARDNESS	1		\$88.78	?
29	FRONT BUMPER LOWER GRILLE	1		<i>su</i> \$102.80	X
30	FRONT BUMPER NUMBER PLATE GARNISH	1		<i>mi</i> \$29.91	✓
31	FRONT BUMPER UNDER COVER	1		<i>su</i> \$186.92	X
32	FRONT BUMPER CENTER UPPER BRACKET LH	1		\$12.15	?
33	FRONT BUMPER CENTER UPPER BRACKET RH	1		\$12.15	?

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 18/11/2022
 Vehicle No: SNB8157C
 Model: TESLA MODEL 3 PERFORMANCE
 Chassis: LRW3F7EL6MC283030 - 2021
 Reg.Year: 2021
 Policy No: SP2000621238-01
 Date of Accident: 16/11/2022

TO MOTOR CLAIM DEPT
 ALLIANZ INSURANCE SINGAPORE
 79 Robinson road, #09-01
 Singapore 068897

34	FRONT BUMPER SPONGE	1		\$46.73	?
35	FRONT BUMPER REINFORCEMENT	1		R \$271.03	X
36	FRONT BUMPER REINFORCEMENT CRUSH CAN LH	1		R \$52.34	X
37	FRONT BUMPER REINFORCEMENT CRUSH CAN RH	1		R \$52.34	X
38	FRONT BUMPER REINFORCEMENT BOLT	2	\$0.74	RR \$1.48	X
39	FRONT BUMPER LOWER REINFORCEMENT	1		R \$102.80	X
40	FRONT BUMPER LOWER CRUSH CAN LH	1		R \$29.91	X
41	FRONT BUMPER LOWER CRUSH CAN RH	1		R \$29.91	X
42	FRONT RADAR SENSOR	1		\$345.79	?
43	FRONT RADAR SENSOR BRACKET	1		\$4.67	?
44	FRONT RADAR SENSOR SUPPORT BRACKET	1		\$7.48	?
45	FRONT RADAR SENSOR WIRE HARDNESS	1		\$93.46	?
46	FRONT SUPPORT PANEL	1		CM \$738.32	✓
47	FRONT SUPPORT PANEL BRACKET LH	1		CM \$7.48	✓
48	FRONT SUPPORT PANEL BRACKET RH	1		CM \$7.48	✓
49	FRONT BATTERY BACKED SIREN ASSY	1		\$44.86	?
50	FRONT AIR GRILLE SHUTTER ASSY	1		\$186.92	?
51	FRONT A/C CONDENSER	1		\$420.56	?
52	FRONT A/C CONDENSER FAN GUARD	1		\$373.83	?
53	FRONT A/C CONDENSER DISCHARGE PIPE	1		\$224.30	?
54	FRONT A/C CONDENSER PRESSURE PIPE	1		\$252.34	?
55	FRONT FENDER LH	1		R1 \$448.60	✓
56	FRONT FENDER RH	1		R1 \$448.60	✓
57	FRONT FENDER INNER SHIELD LH	1		R2 \$116.82	X
58	FRONT FENDER INNER SHIELD RH	1		\$116.82	?
59	FRONT FENDER SUPPORT LH	1		\$23.36	?
60	FRONT FENDER SUPPORT RH	1		\$23.36	?
61	FRONT DOOR LH	1		REPAIR	
62	FRONT DOOR RH	1		REPAIR	
				SUB TOTAL	\$12,022.59
				COST +10%	\$1,202.26
				PARTS TOTAL	\$13,224.85

Date : 18/11/2022
 Vehicle No: SNB8157C
 Model: TESLA MODEL 3 PERFORMANCE
 Chassis: LRW3F7EL6MC283030 - 2021
 Reg.Year: 2021
 Policy No: SP2000621238-01
 Date of Accident: 16/11/2022

TO MOTOR CLAIM DEPT
 ALLIANZ INSURANCE SINGAPORE
 79 Robinson road, #09-01
 Singapore 068897

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		<i>nn</i> \$50.00 ✓
2	FRONT WINDSCREEN SEALANT	1		<i>nn</i> \$100.00 <i>40sn</i>
3	FRONT NUMBER PLATE WITH HOLDER	1		<i>ni's</i> \$50.00 <i>45sn</i>
4	FRONT BUMPER UNDER COVER CLIPS	1		<i>nn</i> \$50.00 X
5	FRONT FENDER INNER SHIELD CLIPS LH	1		<i>nn</i> \$40.00 X
6	FRONT FENDER INNER SHIELD CLIPS RH	1		\$40.00 ?
S/N TOTAL				\$330.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS	\$1,400.00	<i>700</i>
LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS	\$1,400.00	<i>880</i>
LABOUR CHARGES TO REMOVE & REPLACE FRONT WINDSCREEN GLASS & ETC.	\$150.00	<i>120</i>
LABOUR CHARGES TO REMOVE & REPLACE FRONT PARKING SENSOR.	\$120.00	<i>60</i>
LABOUR CHARGES TO REMOVE & REFL A/C GASS & ETC.	\$120.00	<i>?</i>
TO DAIGNOSIS FAULT CODE & RESET MEMORY.	\$300.00	<i>?</i>
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$150.00	<i>20</i>
TO TUFF KOTE & UNDERSEAL MATERIALS.	<i>nz</i> \$100.00	X

LABOUR TOTAL \$3,740.00

KIT TOTAL \$17,294.85

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

