



Date : 18/11/2022  
Vehicle No: SNB8157C  
Model: TESLA MODEL 3 PERFORMANCE  
Chassis: LRW3F7EL6MC283030 - 2021  
Reg.Year: 2021  
Policy No: SP2000621238-01  
Date of Accident: 16/11/2022  
Estimator: KIT

TO MOTOR CLAIM DEPT  
ALLIANZ INSURANCE SINGAPORE  
79 Robinson road, #09-01  
Singapore 068897

*Not Authorized  
Repair B & paint  
7 days Ex \$1500k*

### ESTIMATE

| NO. | DESCRIPTION                             | QTY | UNIT S\$      | AMOUNT S\$        |
|-----|---|-----|---------------|-------------------|
| 1   | FRONT BONNET                            | 1   | ✓             | By \$663.55       |
| 2   | FRONT BONNET "TESLA" EMBLEM             | 1   | ✓             | na \$48.60        |
| 3   | FRONT BONNET HINGE LH                   | 1   | ✓             | DIY \$74.77       |
| 4   | FRONT BONNET HINGE RH                   | 1   | ✓             | DIY \$74.77       |
| 5   | FRONT BONNET STRUT LH                   | 1   | ✓             | Pu \$52.34        |
| 6   | FRONT BONNET STRUT RH                   | 1   | ✓ 52.33       | Pu \$52.34        |
| 7   | FRONT BONNET LOCK                       | 1   | ✓             | By \$177.57       |
| 8   | FRONT BONNET LOCK ACTUATOR              | 1   | ✓             | na \$107.48       |
| 9   | FRONT BONNET LOCK STRIKER               | 1   | ✓             | DIY \$2.80        |
| 10  | FRONT LUGGAGE COMPARTMENT               | 1   | ✓             | Reform \$64.49    |
| 11  | FRONT LUGGAGE COMPARTMENT REINFORCEMENT | 1   | ✓             | By \$13.08        |
| 12  | FRONT LUGGAGE COMPARTMENT BRACKET       | 1   | ✓             | By \$2.40         |
| 13  | FRONT LUGGAGE COMPARTMENT SEAL          | 1   | ✓ 46.73       | na \$44.86        |
| 14  | FRONT WINDSCREEN GLASS                  | 1   | ✓ 763         | CM \$785.05       |
| 15  | FRONT HEADLAMP LH                       | 1   | ✓ 1741 mg     | CM \$1,308.41     |
| 16  | FRONT HEADLAMP RH                       | 1   | ✓             | Bro \$1,308.41    |
| 17  | FRONT HEADLAMP LOWER BRACKET LH         | 1   | ✓             | CM \$7.48         |
| 18  | FRONT HEADLAMP LOWER BRACKET RH         | 1   | ✓             | CM \$7.48         |
| 19  | FRONT HEADLAMP WIRE HARDNESS            | 1   | ✓ 93.46       | WT \$88.79        |
| 20  | FRONT BUMPER                            | 1   | ✓ 766         | By \$663.55       |
| 21  | FRONT BUMPER SIDE RETAINER LH           | 1   | ✓             | DIY \$1.87        |
| 22  | FRONT BUMPER SIDE RETAINER RH           | 1   | ✓             | DIY \$1.87        |
| 23  | FRONT BUMPER TOWING COVER               | 1   |               | su \$14.95        |
| 24  | FRONT BUMPER FOG LAMP LH                | 1   | ✓ mg CM       | su \$271.03       |
| 25  | FRONT BUMPER FOG LAMP RH                | 1   | ✓ u           | su \$271.03       |
| 26  | FRONT BUMPER PARKING SENSOR             | 6   | ✓ 654.21 shon | \$163.55 \$981.30 |
| 27  | FRONT BUMPER PARKING SENSOR BRACKET     | 6   | ✓ 18.68 na    | \$4.67 \$28.02    |
| 28  | FRONT BUMPER SENSOR WIRE HARDNESS       | 1   | ✓             | WT \$88.78        |
| 29  | FRONT BUMPER LOWER GRILLE               | 1   | ✓ DIY         | su \$102.80       |
| 30  | FRONT BUMPER NUMBER PLATE GARNISH       | 1   | ✓             | DIY \$29.91       |
| 31  | FRONT BUMPER UNDER COVER                | 1   |               | su \$186.92       |
| 32  | FRONT BUMPER CENTER UPPER BRACKET LH    | 1   | ✓             | By \$12.15        |
| 33  | FRONT BUMPER CENTER UPPER BRACKET RH    | 1   | ✓             | By \$12.15        |

*Handwritten checkmarks and notes on the right side of the table, including 'X' marks and numerical values like '88.79'.*

**Head office**

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

8A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

**Branch (Motor Insurance Claims)**

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 18/11/2022  
 Vehicle No: SNB8157C  
 Model: TESLA MODEL 3 PERFORMANCE  
 Chassis: LRW3F7EL6MC283030 - 2021  
 Reg.Year: 2021  
 Policy No: SP2000621238-01  
 Date of Accident: 16/11/2022

TO MOTOR CLAIM DEPT  
 ALLIANZ INSURANCE SINGAPORE  
 79 Robinson road, #09-01  
 Singapore 068897

|    |   |   |   |        |             |             |   |
|----|---|---|---|--------|-------------|-------------|---|
| 34 | FRONT BUMPER SPONGE                     | 1 | ✓ | CM     | \$46.73     | ✓           |   |
| 35 | FRONT BUMPER REINFORCEMENT              | 1 | ✓ | By R   | \$271.03    | X           |   |
| 36 | FRONT BUMPER REINFORCEMENT CRUSH CAN LH | 1 | ✓ | DIY R  | \$52.34     | X           |   |
| 37 | FRONT BUMPER REINFORCEMENT CRUSH CAN RH | 1 | ✓ | DIY R  | \$52.34     | X           |   |
| 38 | FRONT BUMPER REINFORCEMENT BOLT         | 2 |   | \$0.74 | ~           | \$1.48      | X |
| 39 | FRONT BUMPER LOWER REINFORCEMENT        | 1 |   |        | ~           | \$102.80    | X |
| 40 | FRONT BUMPER LOWER CRUSH CAN LH         | 1 |   |        | ~           | \$29.91     | X |
| 41 | FRONT BUMPER LOWER CRUSH CAN RH         | 1 |   |        | ~           | \$29.91     | X |
| 42 | FRONT RADAR SENSOR                      | 1 | ✓ | Red    | \$345.79    | ✓           |   |
| 43 | FRONT RADAR SENSOR BRACKET              | 1 | ✓ | DIY    | \$4.67      | ✓           |   |
| 44 | FRONT RADAR SENSOR SUPPORT BRACKET      | 1 | ✓ | DIY    | \$7.48      | ✓           |   |
| 45 | FRONT RADAR SENSOR WIRE HARDNESS        | 1 |   | Pin    | \$93.46     | X           |   |
| 46 | FRONT SUPPORT PANEL                     | 1 | ✓ | CM     | \$738.32    | ✓           |   |
| 47 | FRONT SUPPORT PANEL BRACKET LH          | 1 | ✓ | CM     | \$7.48      | ✓           |   |
| 48 | FRONT SUPPORT PANEL BRACKET RH          | 1 | ✓ | CM     | \$7.48      | ✓           |   |
| 49 | FRONT BATTERY BACKED SIREN ASSY         | 1 | ✓ | Short  | \$44.86     | ✓           |   |
| 50 | FRONT AIR GRILLE SHUTTER ASSY           | 1 | ✓ | CM     | \$186.92    | ✓           |   |
| 51 | FRONT A/C CONDENSER                     | 1 |   | Exc    | \$420.56    | X           |   |
| 52 | FRONT A/C CONDENSER FAN GUARD           | 1 |   | Pin    | \$373.83    | X           |   |
| 53 | FRONT A/C CONDENSER DISCHARGE PIPE      | 1 |   | Pin    | \$224.30    | X           |   |
| 54 | FRONT A/C CONDENSER PRESSURE PIPE       | 1 |   | Pin    | \$252.34    | X           |   |
| 55 | FRONT FENDER LH                         | 1 | ✓ | By     | \$448.60    | ✓           |   |
| 56 | FRONT FENDER RH                         | 1 | ✓ | By     | \$448.60    | ✓           |   |
| 57 | FRONT FENDER INNER SHIELD LH            | 1 |   | Pin    | \$116.82    | X           |   |
| 58 | FRONT FENDER INNER SHIELD RH            | 1 | ✓ | Return | \$116.82    | ✓           |   |
| 59 | FRONT FENDER SUPPORT LH                 | 1 | ✓ | DIY    | \$23.36     | 22.43       |   |
| 60 | FRONT FENDER SUPPORT RH                 | 1 | ✓ | DIY    | \$23.36     | 22.43       |   |
| 61 | FRONT DOOR LH                           | 1 |   |        | REPAIR      |             |   |
| 62 | FRONT DOOR RH                           | 1 |   |        | REPAIR      |             |   |
|    |   |   |   |        | SUB TOTAL   | \$12,022.59 |   |
|    |   |   |   |        | COST +10%   | \$1,202.26  |   |
|    |   |   |   |        | PARTS TOTAL | \$13,224.85 |   |

Head office

6 Kung Chong Road Singapore 159143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500  
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 18/11/2022  
Vehicle No: SNB8157C  
Model: TESLA MODEL 3 PERFORMANCE  
Chassis: LRW3F7EL6MC283030 - 2021  
Reg.Year: 2021  
Policy No: SP2000621238-01  
Date of Accident: 16/11/2022

TO MOTOR CLAIM DEPT  
ALLIANZ INSURANCE SINGAPORE  
79 Robinson road, #09-01  
Singapore 068897

| NO. | SPECIAL NETT                       | QTY | UNIT S\$  | AMOUNT S\$       |
|-----|------------------------------------|-----|-----------|------------------|
| 1   | FRONT BUMPER CLIPS                 | 1   |           | na \$50.00 ✓     |
| 2   | FRONT WINDSCREEN SEALANT           | 1   |           | na \$100.00 405m |
| 3   | FRONT NUMBER PLATE WITH HOLDER     | 1   |           | mi \$50.00 45m   |
| 4   | FRONT BUMPER UNDER COVER CLIPS     | 1   |           | na \$50.00 X     |
| 5   | FRONT FENDER INNER SHIELD CLIPS LH | 1   |           | na \$40.00 X     |
| 6   | FRONT FENDER INNER SHIELD CLIPS RH | 1   |           | na \$40.00 X     |
|     |                                    |     | S/N TOTAL | \$330.00         |

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS \$1,400.00 700

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS \$1,400.00 880

LABOUR CHARGES TO REMOVE & REPLACE FRONT WINDSCREEN GLASS & ETC. \$150.00 120

LABOUR CHARGES TO REMOVE & REPLACE FRONT PARKING SENSOR. \$120.00 60

LABOUR CHARGES TO REMOVE & REFILL A/C GASS & ETC. \$120.00 } 370

TO DAIGNOSIS FAULT CODE & RESET MEMORY. \$300.00 }

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$150.00 20

TO TUFF KOTE & UNDERSEAL MATERIALS. NZ \$100.00 X

LABOUR TOTAL \$3,740.00

KIT

TOTAL \$17,294.85

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Parts @ 12301.98  
SN @ 135.00  
Labour @ 2150.00  
\$14586.98

Date: 18/11/2022 TO MOTOR CLAIM DEPT  
 Vehicle No: SNB8157C ALLIANZ INSURANCE SINGAPORE  
 Model: TESLA MODEL 3 PERFORMANCE 79 Robinson road, #09-01  
 Chassis: LRW3F7EL6MC2S3030 - 2021 Singapore 068897  
 Reg Year: 2021  
 Policy No: SP2000621238-01  
 Date of Accident: 16/11/2022

|    |   |   |        |         |          |   |
|----|---|---|--------|---------|----------|---|
| 34 | FRONT BUMPER SPONGE                     | 1 | CM     | \$48.73 | X        |   |
| 35 | FRONT BUMPER REINFORCEMENT              | 1 | A      | R       | \$271.03 | X |
| 36 | FRONT BUMPER REINFORCEMENT CRUSH CAN LH | 1 | air    |         | \$52.34  | X |
| 37 | FRONT BUMPER REINFORCEMENT CRUSH CAN RH | 1 | OPR    |         | \$52.34  | X |
| 38 | FRONT BUMPER REINFORCEMENT BOLT         | 2 | \$0.74 | ~       | \$1.48   | X |
| 39 | FRONT BUMPER LOWER REINFORCEMENT        | 1 | R      |         | \$102.80 | X |
| 40 | FRONT BUMPER LOWER CRUSH CAN LH         | 1 | R      |         | \$29.91  | X |
| 41 | FRONT BUMPER LOWER CRUSH CAN RH         | 1 | R      |         | \$29.91  | X |
| 42 | FRONT RADAR SENSOR                      | 1 | R      |         | \$345.79 | X |
| 43 | FRONT RADAR SENSOR BRACKET              | 1 | DII    |         | \$4.67   | X |
| 44 | FRONT RADAR SENSOR SUPPORT BRACKET      | 1 | DII    |         | \$7.48   | X |
| 45 | FRONT RADAR SENSOR WIRE HARDNESS        | 1 | R      |         | \$93.46  | X |
| 46 | FRONT SUPPORT PANEL                     | 1 | CM     |         | \$738.32 | X |
| 47 | FRONT SUPPORT PANEL BRACKET LH          | 1 | CM     |         | \$7.48   | X |
| 48 | FRONT SUPPORT PANEL BRACKET RH          | 1 | CM     |         | \$7.48   | X |
| 49 | FRONT BATTERY BACKED SIREN ASSY         | 1 | Man    |         | \$44.86  | X |
| 50 | FRONT AIR GRILLE SHUTTER ASSY           | 1 | CM     |         | \$186.92 | X |
| 51 | FRONT A/C CONDENSER                     | 1 | R      |         | \$420.56 | X |
| 52 | FRONT A/C CONDENSER FAN GUARD           | 1 | R      |         | \$373.83 | X |
| 53 | FRONT A/C CONDENSER DISCHARGE PIPE      | 1 | R      |         | \$224.30 | X |
| 54 | FRONT A/C CONDENSER PRESSURE PIPE       | 1 | R      |         | \$252.34 | X |
| 55 | FRONT FENDER LH                         | 1 | R      |         | \$448.60 | X |
| 56 | FRONT FENDER RH                         | 1 | R      |         | \$448.60 | X |
| 57 | FRONT FENDER INNER SHIELD LH            | 1 | R      |         | \$116.82 | X |
| 58 | FRONT FENDER INNER SHIELD RH            | 1 | Return |         | \$116.82 | X |
| 59 | FRONT FENDER SUPPORT LH                 | 1 | DII    | 22.43   | \$22.36  | X |
| 60 | FRONT FENDER SUPPORT RH                 | 1 | DII    | 22.43   | \$22.36  | X |
| 61 | FRONT DOOR LH                           | 1 |        |         | REPAIR   |   |
| 62 | FRONT DOOR RH                           | 1 |        |         | REPAIR   |   |

✓ 63. Radiator Cooling Fan Module - \$79.44 ✓  
 ✓ 64. Radiator Cooling Fan Shroud - \$84.11 ✓  
 ✓ 65. Cooling Fan Module Assy - \$663.55 ✓

|             |             |
|-------------|-------------|
| SUB TOTAL   | \$12,022.59 |
| COST +10%   | \$1,202.26  |
| PARTS TOTAL | \$13,224.85 |

11087.5  
12196.2



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars     |                                       |
|-------------------------------|---------------------------------------|
| Owner ID Type:                | Singapore NRIC                        |
| Owner ID:                     | 881E                                  |
| Vehicle Details               |                                       |
| Vehicle No.:                  | SNB8157C                              |
| Vehicle to be Exported:       | No                                    |
| Intended Deregistration Date: | 18 Nov 2022                           |
| Vehicle Make:                 | TESLA                                 |
| Vehicle Model:                | MODEL 3 PERFORMANCE                   |
| Primary Colour:               | White                                 |
| Manufacturing Year:           | 2021                                  |
| Engine No.:                   | -                                     |
| Chassis No.:                  | LRW3F7EL6MC283030                     |
| Maximum Power Output:         | 377.0 kW (505 bhp)                    |
| Open Market Value:            | \$72,143.00                           |
| Original Registration Date:   | 15 Sep 2021                           |
| First Registration Date:      | 15 Sep 2021                           |
| Transfer Count:               | 0                                     |
| Actual ARF Paid:              | \$56,858.00                           |
| Intended PARF Rebate Details  |                                       |
| PARF Eligibility:             | Yes                                   |
| PARF Eligibility Expiry Date: | 14 Sep 2031                           |
| PARF Rebate Amount:           | \$42,643.00                           |
| Intended COE Rebate Details   |                                       |
| COE Expiry Date:              | 14 Sep 2031                           |
| COE Category:                 | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years):            | 10                                    |
| QP Paid:                      | \$59,501.00                           |
| COE Rebate Amount:            | \$52,502.00                           |
| <b>Total Rebate Amount:</b>   | <b>\$95,145.00</b>                    |

The information contained herein is correct as at 17 Nov 2022

OK