

ASS. REC. BY:

REF:

AIS / 220116581kqy3

C

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD /  TP /  WS /  TP RES /  OD RES /  EVA /  INV /  MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_ Optima

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: 1500

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$234K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 1.81 % 3 Val.: Yes or No

CA /  REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: PNB 8157C Yr Regn: 09, 21

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Testa Model 3 c.c. \_\_\_\_\_

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 18987 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VINLRW3FFEL6MC 283030

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  Inorder / Jammed / Leaked / Burnt or

Brake:  Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/RIm / STD /  RIm or

Tyre Size: F: 235/35R20

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU /  PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front R/Bal. 8 mm

Rear R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 16/11/22 D.O.I. 21/11/2022

Survey held at \_\_\_\_\_

Des. of Damages:  Frt /  Rear /  O/S /  N/S /  UIC /  Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/3	\$14386.98 Carw 14/3/23 (had \$3534.97, 20%)

Date/Time, File Pass to?  : Prel. Report  : Final Report

Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: 7  
Resurvey No. of Trip: 1

Add Fee:  Site Insp (\$ )  
 Interview (\$ )  
 Tech Invs (\$ )  
 Weekend (\$ )

Survey Fee:	
Transportation:	
\$ - RS. SI	
Fuel	
Others	
TOTAL	

Report Format: MER-00  
Lump Sum / I.B.I: (\$) 14586.98

Date : 18/11/2022  
Vehicle No: SNB8157C  
Model: TESLA MODEL 3 PERFORMANCE  
Chassis: LRW3F7EL6MC283030 - 2021  
Reg.Year: 2021  
Policy No: SP2000621238-01  
Date of Accident: 16/11/2022  
Estimator: KIT

TO MOTOR CLAIM DEPT  
ALLIANZ INSURANCE SINGAPORE  
79 Robinson road, #09-01  
Singapore 068897

*Not Authorized  
Repair B & painting  
7 days Ex \$1500k*

### ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET	1	✓	<i>By</i> \$663.55
2	FRONT BONNET "TESLA" EMBLEM	1	✓	<i>na</i> \$48.60
3	FRONT BONNET HINGE LH	1	✓	<i>DIY</i> \$74.77
4	FRONT BONNET HINGE RH	1	✓	<i>DIY</i> \$74.77
5	FRONT BONNET STRUT LH	1	✓	<i>Pur</i> \$52.34
6	FRONT BONNET STRUT RH	1	✓	<i>Pur</i> \$52.34
7	FRONT BONNET LOCK	1	✓	<i>By</i> \$177.57
8	FRONT BONNET LOCK ACTUATOR	1	✓	<i>na</i> \$107.48
9	FRONT BONNET LOCK STRIKER	1	✓	<i>DIY</i> \$2.80
10	FRONT LUGGAGE COMPARTMENT	1	✓	<i>Reform</i> \$64.49
11	FRONT LUGGAGE COMPARTMENT REINFORCEMENT	1	✓	<i>By</i> \$13.08
12	FRONT LUGGAGE COMPARTMENT BRACKET	1	✓	<i>By</i> \$2.40
13	FRONT LUGGAGE COMPARTMENT SEAL	1	✓ <i>46.73</i>	<i>na</i> \$44.86
14	FRONT WINDSCREEN GLASS	1	✓ <i>763</i>	<i>CM</i> \$785.05
15	FRONT HEADLAMP LH	1	✓ <i>1741 mg</i>	<i>CM</i> \$1,308.41
16	FRONT HEADLAMP RH	1	✓	<i>Bro</i> \$1,308.41
17	FRONT HEADLAMP LOWER BRACKET LH	1	✓	<i>CM</i> \$7.48
18	FRONT HEADLAMP LOWER BRACKET RH	1	✓	<i>CM</i> \$7.48
19	FRONT HEADLAMP WIRE HARDNESS	<i>93.46</i>	1 ✓	<i>WT</i> \$88.79
20	FRONT BUMPER	1	✓ <i>766</i>	<i>By</i> \$663.55
21	FRONT BUMPER SIDE RETAINER LH	1	✓	<i>DIY</i> \$1.87
22	FRONT BUMPER SIDE RETAINER RH	1	✓	<i>DIY</i> \$1.87
23	FRONT BUMPER TOWING COVER	1		<i>su</i> \$14.95
24	FRONT BUMPER FOG LAMP LH	1	✓ <i>mg CM</i>	<i>By</i> \$271.03
25	FRONT BUMPER FOG LAMP RH	1	✓ <i>u</i>	<i>By</i> \$271.03
26	FRONT BUMPER PARKING SENSOR	<i>6</i>	✓ <i>4</i>	\$163.55
27	FRONT BUMPER PARKING SENSOR BRACKET	<i>6</i>	✓ <i>4</i>	\$4.67
28	FRONT BUMPER SENSOR WIRE HARDNESS	1	✓	<i>WT</i> \$88.78
29	FRONT BUMPER LOWER GRILLE	1	✓ <i>DIY</i>	<i>su</i> \$102.80
30	FRONT BUMPER NUMBER PLATE GARNISH	1	✓	<i>DIY</i> \$29.91
31	FRONT BUMPER UNDER COVER	1		<i>su</i> \$186.92
32	FRONT BUMPER CENTER UPPER BRACKET LH	1	✓	<i>By</i> \$12.15
33	FRONT BUMPER CENTER UPPER BRACKET RH	1	✓	<i>By</i> \$12.15

*Handwritten checkmarks and notes on the right side of the table, including 'X' marks and numerical values like '88.79'.*

Date : 18/11/2022  
 Vehicle No: SNB8157C  
 Model: TESLA MODEL 3 PERFORMANCE  
 Chassis: LRW3F7EL6MC283030 - 2021  
 Reg.Year: 2021  
 Policy No: SP2000621238-01  
 Date of Accident: 16/11/2022

TO MOTOR CLAIM DEPT  
 ALLIANZ INSURANCE SINGAPORE  
 79 Robinson road, #09-01  
 Singapore 068897

34	FRONT BUMPER SPONGE	1	✓	CM	\$46.73	✓	
35	FRONT BUMPER REINFORCEMENT	1	✓	By R	\$271.03	X	
36	FRONT BUMPER REINFORCEMENT CRUSH CAN LH	1	✓	Diy R	\$52.34	X	
37	FRONT BUMPER REINFORCEMENT CRUSH CAN RH	1	✓	Diy R	\$52.34	X	
38	FRONT BUMPER REINFORCEMENT BOLT	2		\$0.74	~	\$1.48	X
39	FRONT BUMPER LOWER REINFORCEMENT	1			~	\$102.80	X
40	FRONT BUMPER LOWER CRUSH CAN LH	1			~	\$29.91	X
41	FRONT BUMPER LOWER CRUSH CAN RH	1			~	\$29.91	X
42	FRONT RADAR SENSOR	1	✓	Red	\$345.79	✓	
43	FRONT RADAR SENSOR BRACKET	1	✓	Diy	\$4.67	✓	
44	FRONT RADAR SENSOR SUPPORT BRACKET	1	✓	Diy	\$7.48	✓	
45	FRONT RADAR SENSOR WIRE HARDNESS	1		Pin	\$93.46	X	
46	FRONT SUPPORT PANEL	1	✓	CM	\$738.32	✓	
47	FRONT SUPPORT PANEL BRACKET LH	1	✓	CM	\$7.48	✓	
48	FRONT SUPPORT PANEL BRACKET RH	1	✓	CM	\$7.48	✓	
49	FRONT BATTERY BACKED SIREN ASSY	1	✓	Short	\$44.86	✓	
50	FRONT AIR GRILLE SHUTTER ASSY	1	✓	CM	\$186.92	✓	
51	FRONT A/C CONDENSER	1		Exc	\$420.56	X	
52	FRONT A/C CONDENSER FAN GUARD	1		Pin	\$373.83	X	
53	FRONT A/C CONDENSER DISCHARGE PIPE	1		Pin	\$224.30	X	
54	FRONT A/C CONDENSER PRESSURE PIPE	1		Pin	\$252.34	X	
55	FRONT FENDER LH	1	✓	By	\$448.60	✓	
56	FRONT FENDER RH	1	✓	By	\$448.60	✓	
57	FRONT FENDER INNER SHIELD LH	1		Pin	\$116.82	X	
58	FRONT FENDER INNER SHIELD RH	1	✓	Return	\$116.82	✓	
59	FRONT FENDER SUPPORT LH	1	✓	Diy	\$23.36	22.43	
60	FRONT FENDER SUPPORT RH	1	✓	Diy	\$23.36	22.43	
61	FRONT DOOR LH	1			REPAIR		
62	FRONT DOOR RH	1			REPAIR		
					SUB TOTAL	\$12,022.59	
					COST +10%	\$1,202.26	
					PARTS TOTAL	\$13,224.85	

Head office

6 Kung Chong Road Singapore 159143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500  
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 18/11/2022  
Vehicle No: SNB8157C  
Model: TESLA MODEL 3 PERFORMANCE  
Chassis: LRW3F7EL6MC283030 - 2021  
Reg.Year: 2021  
Policy No: SP2000621238-01  
Date of Accident: 16/11/2022

TO MOTOR CLAIM DEPT  
ALLIANZ INSURANCE SINGAPORE  
79 Robinson road, #09-01  
Singapore 068897

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		na \$50.00 ✓
2	FRONT WINDSCREEN SEALANT	1		na \$100.00 405m
3	FRONT NUMBER PLATE WITH HOLDER	1		mi \$50.00 45m
4	FRONT BUMPER UNDER COVER CLIPS	1		na \$50.00 X
5	FRONT FENDER INNER SHIELD CLIPS LH	1		na \$40.00 X
6	FRONT FENDER INNER SHIELD CLIPS RH	1		na \$40.00 X
			S/N TOTAL	\$330.00

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS \$1,400.00 700

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS \$1,400.00 880

LABOUR CHARGES TO REMOVE & REPLACE FRONT WINDSCREEN GLASS & ETC. \$150.00 120

LABOUR CHARGES TO REMOVE & REPLACE FRONT PARKING SENSOR. \$120.00 60

LABOUR CHARGES TO REMOVE & REFILL A/C GASS & ETC. \$120.00 } 370

TO DAIGNOSIS FAULT CODE & RESET MEMORY. \$300.00 }

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$150.00 20

TO TUFF KOTE & UNDERSEAL MATERIALS. NZ \$100.00 X

LABOUR TOTAL \$3,740.00

KIT

TOTAL \$17,294.85

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Parts @ 12301.98  
SN @ 135.00  
Labour @ 2150.00  
\$14586.98



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	881E
Vehicle Details	
Vehicle No.:	SNB8157C
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Nov 2022
Vehicle Make:	TESLA
Vehicle Model:	MODEL 3 PERFORMANCE
Primary Colour:	White
Manufacturing Year:	2021
Engine No.:	-
Chassis No.:	LRW3F7EL6MC283030
Maximum Power Output:	377.0 kW (505 bhp)
Open Market Value:	\$72,143.00
Original Registration Date:	15 Sep 2021
First Registration Date:	15 Sep 2021
Transfer Count:	0
Actual ARF Paid:	\$56,858.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Sep 2031
PARF Rebate Amount:	\$42,643.00
Intended COE Rebate Details	
COE Expiry Date:	14 Sep 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$59,501.00
COE Rebate Amount:	\$52,502.00
<b>Total Rebate Amount:</b>	<b>\$95,145.00</b>

The information contained herein is correct as at 17 Nov 2022

OK