

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

HOME SOLUTIONS SG
540 ANG MO KIO AVE 10 #04-2398 CHENG
SAN GREEN
SINGAPORE 560540

Contact : 94575381

TAX INVOICE

Repair Code : CLM15728

Date in : 17/11/2022

Vehicle Num. : GBL4757L

Model : NISSAN NV200 1.6DX VANETTE AUTO

Chassis/Eng# : VM20169299/HR16191096D

TP A x A

Xiao Tong

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Rehd</i>	1	524.80	✓ 524.80
REAR BUMPER SIDE RETAINER L/R <i>neu</i>	2	37.20	✓ 74.40
REAR BUMPER SPONGE <i>Amhd</i>	1	94.00	✓ 94.00
REAR BUMPER TOW HOOK COVER <i>neu</i>	1	16.00	+ 16.00
REAR END PANEL (INNER) <i>Rehd</i>	1	576.00	+ 576.00
REAR END PANEL (OUTER) <i>Rehd</i>	1	167.00	✓ 167.00
REAR END PANEL INNER TOP GARNISH <i>Amhd</i>	1	70.00	✓ 70.00
REAR TAILGATE <i>Dented</i>	1	1891.30	1635 1891.30
REAR TAILGATE 'LOGO' EMBLEM <i>neu</i>	1	64.90	✓ 64.90
REAR TAILGATE 'NV200' EMBLEM <i>neu</i>	1	64.90	✓ 64.90
REAR TAILGATE 'VANETTE' EMBLEM <i>neu</i>	1	94.50	✓ 94.50
REAR TAILGATE INNER PULL GARNISH HANDLE <i>neu</i>	1	52.00	+ 52.00
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>neu</i>	2	20.00	+ 40.00
REAR TAILGATE INNER TRIM BOARD <i>torn</i>	1	298.00	138 298.00
REAR TAILGATE LOCK STRIKER <i>neu</i>	1	45.00	+ 45.00
REAR TAILGATE MECHANISM LOCK <i>Dmgd</i>	1	288.90	✓ 288.90
REAR TAILGATE MECHANISM LOCK SIDE COVER L/R <i>neu</i>	2	22.00	+ 44.00
REAR TAILGATE NUMBER PLATE LAMP L/R <i>neu</i>	2	25.00	+ 50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

HOME SOLUTIONS SG
 540 ANG MO KIO AVE 10 #04-2398 CHENG
 SAN GREEN
 SINGAPORE 560540

Contact : 94575381

TAX INVOICE

Repair Code : CLM15728

Date in : 17/11/2022

Vehicle Num. : GBL4757L

Model : NISSAN NV200 1.6DX VANETTE AUTO

Chassis/Eng# : VM20169299/HR16191096D

REAR TAILGATE OUTER GARNISH	<i>cnld</i>	1	352.00	✓ 352.00
REAR TAILGATE WEATHER STRIP	<i>ct</i>	1	88.40	✓ 88.40
REAR TAILLAMP L/R	<i>cnld.</i>	2	258.00	✓ 516.00
Subtotal before discount				5,412.10
Percentage discount 10%				541.21

Sub-total 1

4,870.89

REAR BUMPER CLIPS - SET	<i>ren</i>	1	50.00	<i>30</i> 50.00
REAR END PANEL INNER LOWER GARNISH CLIPS - SET	<i>ren</i>	1	40.00	<i>x</i> 40.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>ren</i>	1	40.00	<i>20</i> 40.00
REAR END PANEL SEALANT	<i>ren</i>	1	100.00	<i>60</i> 100.00
REAR FLOOR PANEL TOP TRIM CARPET	<i>ren</i>	1	400.00	<i>x</i> 400.00
REAR TAILGATE '5 PAX' STICKER	<i>ren</i>	1	25.00	<i>15</i> 25.00
REAR TAILGATE '70KM' STICKER	<i>ren</i>	1	25.00	<i>15</i> 25.00
REAR TAILGATE 'ART WORK DETAIL' STICKER	<i>ren</i>	1	800.00	<i>500</i> 800.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	<i>ren</i>	1	50.00	<i>30</i> 50.00
REAR TAILGATE NUMBER PLATE	<i>ren</i>	1	25.00	<i>x</i> 25.00
REAR TAILGATE NUMBER PLATE HOLDER	<i>ren</i>	1	50.00	<i>x</i> 50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	<i>ren</i>	1	40.00	<i>20</i> 40.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

HOME SOLUTIONS SG
540 ANG MO KIO AVE 10 #04-2398 CHENG
SAN GREEN
SINGAPORE 560540

Contact : 94575381

TAX INVOICE

Repair Code : CLM15728

Date in : 17/11/2022

Vehicle Num. : GBL4757L

Model : NISSAN NV200 1.6DX VANETTE AUTO

Chassis/Eng# : VM20169299/HR16191096D

REAR TAILGATE REVERSE CAMERA	1	500.00	500.00
REAR TAILGATE WINDSCREEN SEAL	1	80.00	80.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	80.00
REAR TAILLAMP CLIPS L/R - SET	2	25.00	50.00
Subtotal before discount			2,355.00
Percentage discount 0%			0.00
Sub-total 2			2,355.00
Parts-total			7,225.89

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total 2,770.00
Parts & Labour Total 9,995.89

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey this is a computer generated document which requires no signature.***
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

Admin Lj
r/s 21/11/22

06 days

Total: 6380.42

4/5: 5.1K ✓