

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: Fax: Email:

INSURER : FIRST CAPITAL INSURANCE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	
Policy No:	5115318061-02	Date of Loss:	13/11/2022
Vehicle Reg. No.:	GBK908A	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SHD6280C
Any Injuries?	no	Contact No:	
Insured/Claimant:	VINJOE ENGINEERING & CONSTRUCTION PTE LTD	Driver:	LEE JUNYI

PARTS MODEL

Make/Model:	Mitsubishi, L200 - MMBENKB40	Vehicle Reg. Date:	18/01/2019
Vehicle Colour:		Engine Number:	
Chassis No:	MMCJJKL20JH016368	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss Collision - Change/cross lane
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	9,581.90
Miscellaneous Items	105.00
Labour	3,430.00
Paintwork Labour	1,140.00
Towing	0.00
Gross Total(S\$):	14,256.90
GST 7.00%(S\$):	997.98
Nett Amount(S\$):	15,254.88

This claim is handled by: Sky Toh T C

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR SPRING LEAF RH ? ✓ BT	2,800.00	1140 ✓ -10.00	2,520.00
2	2	REAR SPRING LEAF U-BOLT RH ✓ BT	140.00	✓ -10.00	126.00
3	1	REAR SPRING LEAF CENTRE PIN RH ✓ BT	150.00	✓ -10.00	135.00
4	4	REAR SPRING LEAF BUSHING RH ? X nn	80.00	-10.00	72.00
5	1	REAR EXHAUST PIPE	2,650.00	960 ✓ -10.00	2,385.00
6	1	REAR NUMBER PLATE END PANEL	680.00	-10.00	612.00
7	1	REAR TAIL BOARD X Repair	1,050.00	-10.00	945.00
8	1	REAR TAIL BOARD LOGO	68.55	✓ -10.00	61.70
9	1	REAR TAIL BOARD SPORTERO EMBLEM	75.00	✓ -10.00	67.50
10	1	REAR TAIL BOARD D1-D EMBLEM	73.00	✓ -10.00	65.70
11	1	REAR SIDE BOARD PANEL RH X Repair	1,450.00	-10.00	1,305.00
12	1	REAR SIDE BOARD PANEL INNER SHIELD RH ✓ DM	130.00	✓ -10.00	117.00
13	1	REAR CARRIAGE FLOOR PANEL X nn	1,300.00	-10.00	1,170.00
			2736.55		
			-10%		
			2462.89		
			Total Parts (S\$)		9,581.90

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	2	REAR EXHAUST PIPE MOUNTING ✓ BT	60.00	0.00	60.00
2	1	REAR NUMBER PLATE ✓ GT	45.00	0.00	45.00
			Sub Total (S\$)		105.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00
2	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	0.00	180.00
3	1	To Dismantle and Refit Rear Undercarriage.	220.00	0.00	220.00
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	3,000.00	0.00	3,000.00
			Gross Labour Cost (S\$)		3,430.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	80.00	0.00	80.00
2	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	60.00	0.00	60.00
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and	1,000.00	0.00	1,000.00

ates On Paint Work Labour

Qty

Particulars

Amount

%Disc

After

Disc

Sanding of Surfaces, Final Polishing and
Waxing are also available.

Gross Labour Cost (S\$)

1,140.00

1410

< END OF ESTIMATES >

3962.89

L/S - 3170.31
=3200

5 Days.

Unpainted

After unpainted photos.

Eno Qial

8288 028 2

28/11/22

YEW TEE AUTOMOBILE TECH PTE LTD

Branch: MEGA@WOODLANDS, 39 Woodlands close #01-12 S(737856)

TEL: 6256 2081 FAX: 6253 2533

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
1	REAR AXEL / BT (New & old part photos)	\$ 3,511.00
Total:		\$ 3,511.00

REMARK: GBK908A

Tail/lamp R/L /