

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
	INCOME INSURAN	ICE LTD	Ref:	CS3/INC22007131/Tvy3m4-1
	75 BRAS BASAH R	ROAD SINGAPORE 189557	Date:	01/12/2022
	ATTN: EILEEN LEE		Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	YQ 4578M	Veh. Inspected	SMN 3560C
	Policy No.		Coverage (\$)	0.00
	Claim No.	MT/CA/TP/036/1181459-001/EL	Excess (\$)	0.00
	Assign From		Assign Date	21/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JTDZS3EU20J038631	Colour	GREY
	Odometer	110017 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	INTERTRAC	7 mm
	L/H Front Tyre	205/60 R16	INTERTRAC	7 mm
	R/H Rear Tyre	205/60 R16	INTERTRAC	7 mm
	L/H Rear Tyre	205/60 R16	INTERTRAC	7 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	22/07/2022	Inspection Date	26/07/2022
	Survey held at	SV AUTOWORKS PTE LTD		
		8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			