



Estimation

Date

Vehicle SJV 5698 U

Make/Model HONDA FIT

Chassis No. GE61206613

No.	Description	Unit	Unit Price	Amount
Parts Replacment				
1	BONNET LOCK X <i>nn</i>	1	\$ 105.00	\$ 105.00
2	HEADLAMP L+R <i>cut</i>	1	\$ 769.00	\$ 769.00
3	HEADLAMP BRACKET L+R X <i>nn</i>	1	\$ 53.00	\$ 53.00
4	FRONT BUMPER RETAINER RH X <i>nn</i>	1	\$ 49.00	\$ 49.00
5	FRONT BUMPER REINFORCEMENT BAR <i>BT</i>	1	\$ 299.00	\$ 299.00
6	FRONT BUMPER UNDERCOVER X	1	\$ 158.00	\$ 158.00
7	FRONT FENDER L+R X	2	\$ 572.00	\$ 1,144.00
8	FRONT FENDER COWLING L+R X	2	\$ 109.00	\$ 218.00
9	FRONT SUPPORT PANEL X <i>nn</i>	1	\$ 590.00	\$ 590.00
10	FRONT SUPPORT PANEL TOP GARNISH X	1	\$ 35.00	\$ 35.00
11	AIRCON CONDENSOR X	1	\$ 855.00	\$ 855.00
12	WIPER WASHER TANK X	1	\$ 95.00	\$ 95.00
Total				\$ 4,370.00
Less 20%				\$ 874.00
Total				\$ 3,496.00

1068
-20%
854.40

S/Nett Items				
1	BONNET <i>CHA</i>	1	2200	\$ 2,200.00
2	FRONT GRILLE X <i>nn</i>	1	600	\$ 600.00
3	FRONT GRILLE LOGO - MUGEN <i>MC</i>	1	150	\$ 150.00
4	FRONT BUMPER <i>CHA</i>	1	2500	\$ 2,500.00
5	FRONT BUMPER TOW COVER <i>MC</i> (C/w bumper) X <i>nn</i>	1	150	\$ 150.00
6	FRONT BUMPER FOG LAMP SET X <i>nn</i>	1	600	\$ 600.00
7	FRONT NUMBER PLATE <i>BT</i>	1	80	\$ 80.00
8	FRONT BUMPER CLIPS <i>MC</i>	1	100	\$ 100.00
9	FRONT FENDER COWLING CLIPS X	1	100	\$ 100.00
10	FRONT SUPPORT PANEL TOP GARNISH CLIPS X <i>nn</i>	1	100	\$ 100.00
Total				\$ 380.00

1890

LABOUR				
1	PANEL BEATING ON AFFECTED AREAS	1	1000	\$ 1,000.00
2	SPRAY PAINT ON AFFECTED AREAS	1	1000	\$ 1,000.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	1	150	\$ 150.00
4	TO RNR INNER TRIM AND UPHOISTERY	1	200	\$ 200.00
5	TO CHECK WATER LEAK	1	150	\$ 150.00

400
400
30
X
X *nn*

6	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS	1	300	\$	300.00
7	TO PERFORM RUST PROOFING	1	100	\$	100.00
8	TO RNR HORN AND TEST FUNCTION	1	150	\$	150.00
Total Labour				\$	3,050.00
Parts Replacement Amount				\$	3,876.00
Total Amount				\$	6,926.00

X
X } are
X

830

4 Days.

4/5

After repair photos.

Geo Ricup

23/11/22

3574.40

L/S - 2859.52
= 2850

LKK Auto Consultants hence notify
the Repairer of the following:

- before/after spray painting
- control during resurvey
- information
- "judice" basis
- A.C.
- insured and
- Insurance Company

Acknowledging Repairer
Signature:
Date: