

08/11/13 wef

ASS. REC. BY: Marcus

REF:

CS/SMO 22011670/Ug43

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN/OUT

Date / Time

Action / Instruction

Dep 12K.

5/5/23

have video at Police

H/S \$1000 informed Florence (head \$6185.50, 862)

Veh No:

SKW2155Y

Yr Regn:

22/10/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

VOLKSWAGEN Jetta

C.C

1390

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

194794

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVWZZZ162FM029940

Gen. Cond. Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/40 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

27/10/22

D.O.I.

23/11/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

05 Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1) 05/5/23

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

)

TOTAL

Report Format :

TP

Lump Sum / I.B.: (\$

1000

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

not Allowed 4/5 # 1000
her
23/11/22 2 days.

FC Garage

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #04-03 Singapore 415875

Tel: 65 90110243

CO. Reg. No.: 53409207A

Model : Volkswagen Jetta
Registraion No : SKW 2155 Y
Chassis No: WVVZZZ16FM029940
Year of Manufacturing:

S/No	Qty	Items	Unit Price	Amount
1	1	Front Bumper <i>De/ torn</i>	\$ 713.20	\$ 713.20 ✓
2	2	LHS & RHS Front Bumper Retainer <i>offset</i>	\$ 39.80	\$ 79.60 12c
3	1	Front Bumper Upper Grille <i>11</i>	\$ 463.26	\$ 463.26 X
4	1	Front Bumper Lower Grille <i>11</i>	\$ 255.76	\$ 255.76 X
5	1	Front Bumper Towing Cover <i>11</i>	\$ 38.58	\$ 38.58 X
6	1	Front Bumper Logo <i>11</i>	\$ 153.54	\$ 153.54 X
7	1	LHS Front Bumper Fog Light <i>11</i>	\$ 186.90	\$ 186.90 X
8	1	LHS Front Bumper Fog Light Cover <i>11</i>	\$ 75.21	\$ 75.21 X
9	1	RHS Front Bumper Fog Light <i>11</i>	\$ 186.90	\$ 186.90 X
10	1	RHS Front Bumper Fog Light Cover <i>11</i>	\$ 75.21	\$ 75.21 X
11	1	Front Reinforcement <i>11</i>	\$ 488.61	\$ 488.61 X
12	1	Front Reinforcement Bracket <i>11</i>	\$ 134.86	\$ 134.86 X
13	1	Front Support Panel <i>11</i>	\$ 899.17	\$ 899.17 X
14	1	Support Panel Top Garnish <i>11</i>	\$ 189.70	\$ 189.70 X
18	1	RHS Headlight <i>11</i>	\$ 553.98	\$ 553.98 X
19	1	RHS Headlight Bracket <i>11</i>	\$ 78.30	\$ 78.30 X

\$ 4,572.78

-10% \$ 457.28

Total for spare parts \$ 4,115.50

Special Nett

1	<i>10/12/22</i>	Front bumper clip <i>her</i>	\$ 9.00	\$ 90.00 40
2	10	Support Panel Top Garnish Clip <i>11</i>	\$ 5.00	\$ 50.00 X
3	1	Front no.plate with casing <i>11</i>	\$ 50.00	\$ 50.00 X

Total for SP \$ 190.00

Sub-Total for Parts : \$ 4,305.50

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.	\$	1,000.00 200
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	1,200.00 320

3	Apply rust proofing on the adjacent panels	\$ 11 60.00	X
4	To supply under coating / putty on parts replaced	\$ 11 60.00	X
5	To perform water seepage test after repair	\$ 11 80.00	X
6	To reset engine management system with diagnostic fault	\$ 11 100.00	X
7	Disconned and check electrical wiring, harness, wire socket	\$ 80.00	20
8	To conduct headlight focus	\$ 150.00	
9	Remove and replace air-con condenser, pipes and radiator, vaccum air-con system and refill gas	\$ 11 150.00	X

TOTAL AMOUNT : \$ 2,880.00
OVERALL COST: \$ 7,185.50

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 753
12
677.7

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	763B
Vehicle Details	
Vehicle No.:	SKW2155Y
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Nov 2022
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA GP 1.4 TSI 90 A/T HL 1634G5
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	CAXF56241
Chassis No.:	WVWZZZ16ZFM029940
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,307.00
Original Registration Date:	22 Oct 2015
First Registration Date:	22 Oct 2015
Transfer Count:	2
Actual ARF Paid:	\$19,307.00 9653
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Oct 2025
PARF Rebate Amount:	\$11,584.00
Intended COE Rebate Details	
COE Expiry Date:	21 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,606.00
COE Rebate Amount:	\$16,291.00
Total Rebate Amount:	\$27,875.00

The information contained herein is correct as at 23 Nov 2022

OK