



Section A - Accident Details

Registration Number	SHB5159M
Case Reference Number	TAX/11/22/2042
Registration Date	1/4/2016
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TOH CHENG HUI
Type of Accident	Head To Side
Accident Date and Time	20/11/2022 11:35 AM
Accident Reported Date and Time	21/11/2022 9:34 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116900
Special Instruction to ARC, if any	LEFT REAR PORTION
Prepared Date and Time	21/11/2022 10:58 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$600.00
Total Spray Cost	\$1,854.00	\$800.00
Total Spare Part Cost	\$6,085.90	\$751.74
Total Other Cost	\$740.00	\$90.00
TOTAL COST	\$9,693.90	\$2,241.74
Lump Sum Total	\$9,700.00	\$2,250.00 (L/S)
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Boon Chew Tay	Taufikh(LKK) / AIG
ARC / Surveyor Sign Off Date	21/11/2022 4:42 PM	21/11/2022 4:06 PM
Signature		
Remarks	LUMPSUM REPAIR / RESURVEY AFTER PAINT PHOTOS, FOR CHECK ITEM and REPLACE ITEM. PLEASE CALL SURVEYOR TAUFIKH , HP 9749 5749/ EMAIL: taufikh@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2212-0097	Invoice Number	
Quotation Date	13.12.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION REAR	\$1,014.00	\$600.00
Total Labour	\$1,014.00	\$600.00 ✓

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FUEL LID COVER	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY RIM	\$180.00	\$100.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,854.00	\$800.00 ✓

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00 X nn
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00 X nn
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00 ✓ NEC
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00 ✓ NEC
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00 X nn
TO REMOVE & REFIT REAR QUARTER GLASS LH	\$120.00	\$0.00 X nn
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00 X nn
Total Other Costs	\$740.00	\$90.00 ✓

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$478.90	100.00	\$0.00	Replace	Repair
		90467-07211	BUMPER CLIPS (10 PCS)	0.00	\$2.40	0.00	\$0.00	Replace	Not Given
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$234.70	0.00	\$0.00	Replace	Not Given
		52015-47050	ARM SUB-ASSY. RR BUMPER RH	0.00	\$157.90	0.00	\$0.00	Replace	Not Given
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$157.90	0.00	\$0.00	Replace	Not Given
		89997-30070	ANTENNA,ELECTRICAL LOWER REAR	0.00	\$208.10	0.00	\$0.00	Replace	Not Given

R
X nn
X nn
X nn
X nn
X nn

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 30/12/2022

User ID : PohSuan

			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X nn
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$108.70	0.00	\$0.00	Replace	Check	X nn
		52592-47021	BUMPER SEAL, RR LH	0.00	\$101.80	0.00	\$0.00	Replace	Not Given	X nn
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$93.90	0.00	\$0.00	Replace	Not Given	X nn
		76891-47020	BUMPER LIP REAR	0.00	\$301.90	0.00	\$0.00	Replace	Not Given	X nn
		58307-47060	END PANEL	0.00	\$755.10	0.00	\$0.00	Replace	Not Given	X nn
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X nn
		67004-47080	DOOR RR/LH	1.00	\$1,213.70	25.00	\$910.28	Replace	Replace	√ DD
		61602-47091	FENDER RR/LH	1.00	\$980.80	100.00	\$0.00	Replace	Repair	R X
			STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	√ nec
			STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	√ nec
		62720-47031	QUARTER GLASS RR/LH	0.00	\$192.30	0.00	\$0.00	Replace	Not Given	X nn
			SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X nn
		65638-47021	FENDER LINER R/LH	0.00	\$159.80	0.00	\$0.00	Replace	Not Given	X nn
		81561-47170	TAIL LAMP LH	0.00	\$618.60	0.00	\$0.00	Replace	Not Given	X nn
		52563-47010	TAIL LAMP BRACKET, LH	0.00	\$35.20	0.00	\$0.00	Replace	Not Given	X nn
		75852-47900	MOULDING BODY, LH	1.00	\$761.40	100.00	\$0.00	Replace	Repair	R X
		69060-47080	DOOR LOCK RR/LH	0.00	\$798.80	0.00	\$0.00	Replace	Not Given	X nn
		68780-52031	HINGE LOWER LHR, DOOR	0.00	\$93.90	0.00	\$0.00	Replace	Not Given	X nn
		68760-20122	HINGE UPPER LHR, DOOR	0.00	\$107.00	0.00	\$0.00	Replace	Not Given	X nn
		68630-47031	CHECK ASSY, RR DOOR,	0.00	\$199.40	0.00	\$0.00	Replace	Not Given	X nn
		85720-47130	DOOR REGULATOR MOTOR REAR LH	0.00	\$1,003.80	0.00	\$0.00	Replace	Not Given	X nn
		69802-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR LH	0.00	\$256.60	0.00	\$0.00	Replace	Not Given	X nn
		67872-47030	DOOR WEATHERSTRIP RR/LH	0.00	\$195.20	0.00	\$0.00	Replace	Not Given	X nn
Total					\$9,501.20		\$939.68			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	939.68	
	-20%	
	<u>751.74</u>	L/S \$2,250/-
+	600.00	
+	<u>890.00</u>	
	2,241.74	