

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG22011679/UWY3M4**Date:** 13/12/2022**REFERENCE**

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1002270196

**Claimant Vehicle No :** SMY7254C**Insured Vehicle No :** SME375M

Date of Loss: 18/11/2022

Nature of Claim: TP Claim No: 291646

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMY7254C**

Make &amp; Model: BMW 520I, 2.0 AT D/AB 2WD 4DR LED NAV (A) Engine No: B4390653N20B20B

Reg. Date: 26/09/2014 (Man. Year: 2013)

Chassis No: WBA5A32060D334833

Colour: White

Odometer: 142812 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 245/35 R20

Rear Tyre Size: 245/35 R20

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,369.05	0.00	4,369.05	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,000.00	1,500.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>6,869.05</b>	<b>1,000.00</b>	<b>5,869.05</b>	<b>85.44</b>

**INSPECTION**

Date of Assignment: 22/11/2022

Date Inspected: 22/11/2022 Inspected At:

Zoom Autowerks Pte Ltd (Bedok)  
130 Bedok Reservoir Road, #08-1339  
Singapore 470130

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2022)
Parts:	143	BMW 520I 2.0 AT D/AB 2WD 4DR LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY7254C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -RH	Repair	1,805.00 FL	*- FL
2	1		*FRONT DOOR LOCK	Not Necessary	285.00 FL	*- FL
3	1		*FRONT DOOR SIDE MIRROR	Repair	1,212.00 FL	*- FL
4	1		*FRONT DOOR BLACK TAPE	Not Necessary	167.00 FL	*- FL
5	1		*FRONT DOOR OPENING WEATHERSTRIP	Not Necessary	197.00 FL	*- FL
6	1		*FRONT FENDER -RH	Repair	933.00 FL	*- FL
					Sub Total (S\$)	4,599.00 0.00
					- List Item Discount on L Items 5.00/5.00% (S\$)	229.95 0.00
					Total Parts (S\$)	4,369.05 0.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR	New	200.00	0.00
2	TO APPLY UNDERCOATING	New	100.00	0.00
3	PANEL BEATING	New	1,200.00	400.00
4	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,000.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>2,500.00</b>	<b>1,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >