

28 November 2022

REG NO.: SMY 7254 C
MAKE/MODEL: BMW 520i

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(S\$)
	<u>LIST ITEMS</u>	
1	Front door -RH	\$ 1,805.00
1	Front door lock	\$ 285.00
1	Front door side mirror	\$ 1,212.00
1	Front door black tape	\$ 167.00
1	Front door opening weatherstrip	\$ 197.00
1	Front fender -RH	\$ 933.00
		\$ 4,599.00
	Less 5%	\$ 229.95
		\$ 4,369.05

S/N	LABOUR CHARGES	
1	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$ 200.00
2	To apply undercoating.	\$ 100.00
3	Panel beating.	\$ 1,200.00
4	To re-spray painting on the affected areas.	\$ 1,000.00
		\$ 2,500.00

GRAND TOTAL :

\$ 6,869.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: