⟨ 1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR INSF	PECTION REP	ORT		
	CHINA TAIPING IN	ISURANCE (S) PTE LTD		Ref:	CS/CTI22011681/Tvp3	
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909		Date:	21/11/2022	
				Code:	СТІ	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBL 8824A	Veh. Inspected		SJQ 879Z	
	Policy No.	DMCVSNW00079542200	Coverage (\$)		0.00	
	Claim No.	SNM22D207905/C02	Excess (\$)		0.00	
	Assign From	IRENE TAY	Assign Date		21/11/2022	
2.	. Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.						
	Accident Date	01/11/2022	Inspect Date /	Time	21/11/2022(-)	
	Survey held at	A T PERFORMANCE				
		160 SIN MING DRIVE #07-18/19 SIN MING AUTOCITY SINGAPORE 575722				
5a.		Remarks				
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Report Ref No. CS/CTI22011681/Tvp3

Inspected By

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.