

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts Er	Automo	obile CS3/	CTI2100674
	CHINA TAIPING IN	ISURANCE (S) PTE LTD		Ref:	-003/0TI210	00745/T1qc
	3 ANSON ROAD # SPRINGLEAF TO\	16-00 VERSINGAPORE 079909		Date:	10/00/2021	• 14/11/2022
				Code:	CTI	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XD 4071M	Veh. Inspected	ł	YM 9835J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	SNM21D203233C02	Excess (\$)		0.00	
	Assign From	CHEE SO CHOW LYNN KHONG	Assign Date		10/00/2021	14/11/2022
2.		Vehicle Partic	ulars & Conditi	ion		
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
8.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
١.		Description	on of Damages			
5.	General Information					
	Accident Date	07/06/2021	Inspection Dat		16/06/2021	
	Survey held at	COSMOPOLITAN ENGRG. SER	VICES PTE. LTD.			
		4 LOYANG WALK SINGAPORE 508787				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					