

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22011684/RNP3M4**Date:** 19/04/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00007602201

**Claimant Vehicle No :** EA22Y **Insured Vehicle No :** SMR6782M

Date of Loss: 19/11/2022 Nature of Claim: TP Claim No: SNM22D208312/C02/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **EA22Y**

Make & Model: SUBARU FORESTER, 2.0 I-L CVT AWD SR (A) Engine No: FB201686003

Reg. Date: 31/07/2015 (Man. Year: 2015) Chassis No: JF1SJ5KC5FG052311

Colour: Red Odometer: 127687 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 225/60R17 Rear Tyre Size: 225/60R17

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,822.00	1,540.00	282.00	15.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,300.00	4,690.00	2,610.00	35.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,122.00</b>	<b>6,230.00</b>	<b>2,892.00</b>	<b>31.70</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>729.76</b>	<b>498.40</b>	<b>231.36</b>	<b>31.70</b>
<b>Nett Amount (S\$)</b>	<b>9,851.76</b>	<b>6,728.40</b>	<b>3,123.36</b>	<b>31.70</b>

**INSPECTION**

Date of Assignment: 21/11/2022

Date Inspected: 22/11/2022 Inspected At: MOTOR IMAGE ENTERPRISES PTE LTD  
25 LENG KEE ROAD, SINGAPORE 159097

Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD RASUL**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Apr 2023)
Parts:	M1-SUV	SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EA22Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER LH	Repair	277.50 FN	*- FN
2	1		*PNL COMPL DR F LH	Buckled	740.00 FN	*740.00 FN
3	1		*PNL COMPL DR R LH	Buckled	703.00 FN	*703.00 FN
4	1		*TAPE DR SASH F F LH	Necessary	5.60 FN	*5.60 FN
5	1		*TAPE DR SASH F M LH	Necessary	18.50 FN	*18.50 FN
6	1		*TAPE DR SASH F R LH	Necessary	18.50 FN	*18.50 FN
7	1		*TAPE DR SASH R F LH	Necessary	18.50 FN	*18.50 FN
8	1		*TAPE DR SASH R M LH	Necessary	11.10 FN	*11.10 FN
9	1		*TAPE DR SASH R R LH	Necessary	14.80 FN	*14.80 FN
10	1		*GARNISH F FENDER LH	Scratched	18.50 FN	*18.50 FN
11	1		*GARNISH AY DR F LH	Missing	203.50 FN	*203.50 FN
12	1		*GARNISH AY DR R LH	Scratched	148.00 FN	*148.00 FN
13	1		*SUNDRIES	Necessary	80.00 FS	*20.00 FS
F=Franchise part. S=SpcNett. N=NettItemDisc.						
Sub Total (\$\$)					2,257.50	1,920.00
- Nett Item Discount on N Items 20.00/20.00% (\$\$)					435.50	380.00
Total Parts (\$\$)					1,822.00	1,540.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPAIR AND REPLACE FRONT LHS FENDER, FRONT LHS DOOR, REAR LHS DOOR, AND FRONT LHS ROCKER PANEL	New	2,800.00	1,200.00
2	RESPRAY FRONT LHS FENDER, FRONT LHS DOOR, REAR LHS DOOR AND FRONT LHS ROCKER PANEL	New	2,640.00	1,680.00
3	TRANSFER FRONT LHS DOOR AND REAR LHS DOOR MECHANISM	New	400.00	400.00
4	TO CONDUCT FAULT DIAGNOSTIC AND RESET	New	300.00	250.00
5	REPAIR LHS B PILLAR AND FRONT LHS ROCKER PANEL (SUPP)	New	600.00	600.00
6	RESPRAY FRONT LHS ROCKER PANEL (SUPP)	New	560.00	560.00
<b>Gross Labour Cost (S\$)</b>			<b>7,300.00</b>	<b>4,690.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >