

IMAGE ENTERPRISES PTE. LTD.
LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO EA22Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPAIR AND REPLACE FRONT LHS FENDER, FRONT LHS DOOR, REAR LHS DOOR, AND FRONT LHS ROCKER PANEL	2800.00	1200 ✓
2	ZZ/002	RESPRAY FRONT LHS FENDER, FRONT LHS DOOR, REAR LHS DOOR AND FRONT LHS ROCKER PANEL	2640.00	1680 ✓
3	ZZ/003	TRANSFER FRONT LHS DOOR AND REAR LHS DOOR MECHANISM	400.00	✓
4	ZZ/004	TO CONDUCT FAULT DIAGNOSTIC AND RESET	300.00	250 ✓
5	ZZ/005	SUNDRIES	80.00	20 ✓
TOTAL LABOUR CHARGES			6220.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO EA22Y

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	FRT FENDER LH <i>reput</i>	(W/O SIGNAL LP) 57120SG0309P	277.50			
2	PNL COMPL DR F LH <i>bu</i>	60009SG0529P	740.00	/		
3	PNL COMPL DR R LH <i>bu</i>	60409SG0119P	703.00	/		
4	TAPE DR SASH F F LH <i>re</i>	90422SG010	5.60	/		
5	TAPE DR SASH F M LH <i>re</i>	90422SG030	18.50	/		
6	TAPE DR SASH F R LH <i>re</i>	90422SG050	18.50	/		
7	TAPE DR SASH R F LH <i>re</i>	DT 1PC 90422SG070	18.50	/		
8	TAPE DR SASH R M LH <i>re</i>	90422SG090	11.10	/		
9	TAPE DR SASH R R LH <i>re</i>	90422SG110	14.80	/		
10	GARNISH F FENDER LH <i>sea</i>	91112SG111	18.50	/		
11	GARNISH AY DR F LH <i>MIS</i>	SG131/130 91112SG132	203.50	/		
12	GARNISH AY DR R LH <i>sea</i>	91112SG152	148.00	/		
SUB TOTAL			2177.50	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			435.50	0.00	0.00	0.00
GRAND TOTAL			1742.00	0.00	0.00	0.00
OVERALL TOTAL			1742.00			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO EA22Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPAIR AND REPLACE FRONT LHS FENDER, FRONT LHS DOOR, REAR LHS DOOR, AND FRONT LHS ROCKER PANEL	2800.00	1200.00
2	ZZ/002	RESPRAY FRONT LHS FENDER, FRONT LHS DOOR, REAR LHS DOOR AND FRONT LHS ROCKER PANEL	2640.00	1680.00
3	ZZ/003	TRANSFER FRONT LHS DOOR AND REAR LHS DOOR MECHANISM	400.00	400.00
4	ZZ/004	TO CONDUCT FAULT DIAGNOSTIC AND RESET	300.00	250.00
5	ZZ/005	SUNDRIES	80.00	20.00
6	ZZ/006	* REPAIR LHS 'B' PILLAR AND FRONT LHS ROCKER PANEL (SUPP) *	600.00	600.00 / <i>na</i> /
7	ZZ/007	* RESPRAY FRONT LHS ROCKER PANEL (SUPP) *	560.00	560.00 / <i>na</i> /
TOTAL LABOUR CHARGES			7380.00	4710.00