

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22011690/UPA3Q2**Date:** 06/07/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : SGS7389A**Insured Vehicle No :** SGW9919L

Date of Loss: 20/11/2022

Nature of Claim: TP

Claim No: SP2002471916-01

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGS7389A**

Make & Model: MERCEDES-BENZ C180, 1.8 CGI (A)

Engine No: 27182030079350

Reg. Date: 18/08/2010 (Man. Year: 2010)

Chassis No: WDD2040492A403505

Colour: Blue

Odometer: 142695 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,047.20	2,479.57	4,567.63	64.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	780.00	770.00	49.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,597.20	3,259.57	5,337.63	62.09
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	8,597.20	2,600.00	5,997.20	69.76
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,928.45		

INSPECTION

Date of Assignment: 21/11/2022

Date Inspected: 21/11/2022 Inspected At:

GALAXY AUTO CARE PTE LTD (HQ)
13 KAKI BUKIT ROAD 4, #01-23 BARTLEY BIZ
CENTRE
Singapore 417807

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jul 2023)
Parts:	143	MERCEDES-BENZ C180 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGS7389A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deep Cut	1,556.00 FL	*1,432.30 FL
2	1		*REAR FENDER LH	Repair	1,850.00 FL	*- FL
3	1		*REAR FENDER INNER SHIELD LH	Not Necessary	425.00 FL	*- FL
4	1		*REAR WHEEL BEARING LH	Damaged	545.00 FL	*545.00 FL
5	1		*REAR RIM LH	Warped	2,400.00 FS	*650.00 FS
6	1		*REAR TYRE LH	Serviceable	320.00 FS	*- FS
7	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
8	1		*JOINT SEALANT	Not Necessary	120.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					7,266.00	2,677.30
- List Item Discount on L Items 5.00/10.00% (\$\$)					218.80	197.73
Total Parts (\$\$)					7,047.20	2,479.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	100.00	0.00
2	REMOVE AND REFIT REAR LINING TRIM AND GARNISH	New	150.00	0.00
3	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	New	600.00	200.00
4	SPRAY PAINTING ON AFFECTED AREAS	New	600.00	580.00
5	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	0.00
Gross Labour Cost (\$\$)			1,550.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >