

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO 201001158E

Kp

SNB 6667K

TP/AXA

Not Authorized

Runway B4 claim

3 days

M/S: AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

Estimate No: ES2291260

Date: 05 Dec 2022

Policy No: 5109615693-03

Veh Reg No: SNB6667K

Make/Model: TOYOTA TOYOTA
 VIOS 1.5 E (AUTO)

Chassis No: MR2B23F3201176542

Engine No: 2NRX440187

Reg. Date: 24/05/2019

WS Ref: TP/AXA

Claim Type: Third Party

Accident Date: 15/11/2022

TP Veh Reg No: SMJ1466B

Estimate Repair Cost to Vehicle No :SNB6667K

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	565.60	1 PC	565.60	—
2 REAR BUMPER CLIPS	3.50	6 PCS	21.00	—
3 REAR BOOT LOGO	59.80	1 PC	59.80	—
			646.40	
		Less 30%	193.92	452.48
Special Net				
4 REVERSE SENSOR	200.00	1 SET	200.00	200.00
Labour				
5 REMOVE & REFIX REAR BUMPER ASSY,REFLRCTORS,TO KNOCK & REPAIR REAR PANEL, REAR BOOT AND REALIGN THE SAME	550.00	1 LA	550.00	400
6 PUTTY & RESPRAY REAR PANEL,REAR BUMPER, REAR BOOT	650.00	1 LA	650.00	400
7 TO REMOVE AND REFIX REVERSE CAMERA, SENSOR AND RESET SYSTEM	30.00	1 LA	30.00	—
			1,230.00	1,230.00
			Total	S\$ 1,882.48
			Add GST @ 7%	131.77
			Total Amount Payable	S\$ 2,014.25

Parts \$646.40
 Reverse Sensor \$195.00
 25% \$841.40
 \$210.39
 25% \$631.09
 830
 \$1461.05

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE