

 $51\; UBI\; AVE\; 1, \#02-25\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: (065)\; 62563561\;\; FAX: (065)\; 62564315\;\; FAX: (065)\; 6256415\;\; FAX: (065)\; FAX$

Immediate Advice

To: HSBC Life (Singapore) Pte. Ltd. Date: 07/02/2023

Survey Details:

Date of loss	17-Nov-22	
Date of appointment	21-Nov-22	
Date of survey	23-Nov-22	
Location of survey	ZOOM AUTOWERKS PTE	LTD

Vehicle Details:

Claim Type:	Third party		
Vehicle number	GBJ1237B		
Make and Model	TOYOTA HIACE (2982cc)		
Date of registration	15/1/2019		
Excess			
Market Value/ Book Value	\$	62,000.00	(est)
Parf/COE Rebate	\$	16,897.00	(est)
Nett Value/ ERV	\$	45,103.00	(est)

Repair details:

Initial Estimate	\$	15,570.81
------------------	----	-----------

Proposed/Revised repair cost:

Parts	\$ 4,090.84
Check items (estimate)	NIL
Labour	\$ 1,920.00
Supplementary	NIL
Total	\$ 6,010.84
Lump Sum(if applicable)	\$ 4,800.00

Number of days for repair	<u>5</u>



 $51\ UBI\ AVE\ 1,\#02-25\ PAYA\ UBI\ INDUSTRIAL\ PARK, SINGAPORE\ 408933\ \ TEL: (065)\ 62563561\ \ FAX: (065)\ 62564315$

Remarks:

BOLA 14. OID MOVED OUT FROM STATIONARY POSITION AND
HIT TP WHO WAS DRIVING STRAIGHT

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 4,800.00	
Loss of use	NIL	
Loss of rental	\$ 700.00	(7DAYS X \$100)
Loss of income	NIL	
LTA/GIA search fees	\$ 38.45	
Others	NIL	
Proposed Total	\$ 5,538.45	