

Ass. PEG BY:

REF: CCG/CTI 220116494 D^U 3

ASSIGNMENT

COE NOV 2027

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bel. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: 7/P % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA 6775H

Yr Regn: NOV / 2019

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius

c.c. 1798

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 317562

T/Radio: Insured / Std / NI / NA

Eng/No: 2ZR2F48674

C/No: STDK B3 FU 703089496

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LZA / MEC / OHTSU / PIR / SUMI / TOYO / YOKO or Westlake

Front

Rear

R/Bal: 5 mm

R/Bal: 5 mm

L/Bal: 5 mm

L/Bal: 5 mm

D.O.A. 19/11/2022

D.O.I. 21/11/2022

Survey held at

Biprost Sin Ming

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

China Teiping XE 7908

No used part. Repair on P/Part.

06/06/23

phaser P/P 10,526.72 with 9 days of work.

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

Add Fee:



: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech. Invs (\$ _____)

Report Format: _____

1 senior, 2 junior, 1 P/P to 1/2

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 21-Nov-22

INSURANCE: China Taiping

MODEL: TOYOTA PRIUS G5

VEHICLE NO.: SHA 6775 H

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR BUMPER <i>clashed 1st</i>	1	\$ 642.04	\$642.04
REAR BUMPER CLIPS <i>huc</i>	1	\$ 30.80	\$30.80
REAR BUMPER SIDE CLIP <i>HH</i>	1	\$ 35.00	\$35.00
ARM SUB-ASSY, REAR BUMPER, RH <i>HH</i>	1	\$ 195.44	\$195.44
REAR BUMPER UNDER SIDE COVER (RH) <i>HH</i>	1	\$ 324.80	\$324.80
RETAINER, REAR BUMPER, SIDE, RH <i>HH</i>	1	\$ 132.72	\$132.72
RETAINER, REAR BUMPER, UPPER SIDE (RH) <i>HH</i>	1	\$ 42.98	\$42.98
REAR FENDER, RH <i>Demol</i>	1	\$ 1,171.38	\$1,171.38
REAR FENDER SHIELD (RH) <i>HH</i>	1	\$ 187.88	\$187.88
REAR FENDER ADVERTISEMENT LOGO (RH) <i>huc</i>	1	\$ 140.00	\$140.00
PANEL SUB-ASSY, REAR DOOR, RH <i>Demol</i>	1	\$ 1,761.62	\$1,761.62
REAR DOOR OUTER HANDLE <i>HH</i>	1	\$ 130.20	\$130.20
REAR DOOR HINGE UPPER <i>HH</i>	1	\$ 115.22	\$115.22
REAR DOOR HINGE LOWER <i>HH</i>	1	\$ 115.22	\$115.22
REAR DOOR CHECK <i>HH</i>	1	\$ 214.20	\$214.20
REAR DOOR OUTER MOULDING <i>SH</i>	1	\$ 180.04	\$180.04
REAR DOOR INNER LOCK <i>HH</i>	1	\$ 902.58	\$902.58
REAR DOOR RUBBER SEAL OUTER <i>SH</i>	1	\$ 361.06	\$361.06
MOTOR, POWER WINDOW REGULATOR FRT, RH <i>HH</i>	1	\$ 1,318.52	\$1,318.52
REGULATOR, FRONT DOOR WINDOW REAR, RH <i>HH</i>	1	\$ 319.76	\$319.76
MOULDING, FRONT DOOR WINDOW FRAME, REAR RH <i>HH</i>	1	\$ 75.18	\$75.18
PANEL SUB-ASSY, FRONT DOOR, RH <i>Demol</i>	1	\$ 1,769.60	\$1,769.60
FRONT DOOR OUTER HANDLE (RH) <i>cut</i>	1	\$ 530.46	\$530.46
FRONT DOOR INNER LOCK <i>HH</i>	1	\$ 964.32	\$964.32
FRONT DOOR HINGE UPPER <i>HH</i>	1	\$ 115.22	\$115.22
FRONT DOOR HINGE LOWER <i>HH</i>	1	\$ 127.68	\$127.68
FRONT DOOR CHECK <i>HH</i>	1	\$ 214.93	\$214.93
FRONT DOOR OUTER MOULDING <i>SH</i>	1	\$ 264.04	\$264.04
FRONT DOOR WHETHER STRIP <i>SH</i>	1	\$ 641.06	\$641.06
FRONT DOOR RUBBER SEAL <i>HH</i>	1	\$ 359.80	\$359.80
MOTOR ASSY, POWER WINDOW FRT, RH <i>HH</i>	1	\$ 1,318.52	\$1,318.52
REGULATOR, FRONT DOOR WINDOW FRT, RH <i>HH</i>	1	\$ 319.76	\$319.76
MIRROR ASSY, OUTER REAR VIEW, RH <i>HH</i>	1	\$ 2,420.18	\$2,420.18
FRONT DOOR ADVERTISEMENT LOGO <i>huc</i>	1	\$ 140.00	\$140.00
FRONT DOOR COMFORT LOGO <i>huc</i>	1	\$ 105.00	\$105.00
CENTRE ROCKER PANEL (GARNISH) <i>HH</i>	1	\$ 806.40	\$806.40

REAR TYRE (RH) <i>SN</i>	1	\$ 302.40	\$302.40	X
REAR TYRE RIM (RH) <i>cut 1570.55</i>	1	\$ 2,177.00	\$2,177.00	✓
REAR WHEEL CAP (RH) <i>HF</i>	1	\$ 248.78	\$248.78	X
REAR WHEEL BEARING HUB <i>Daw o/s 493.70</i>	1	\$ 854.28	\$854.28	✓
REAR SHOCK ABSORBER <i>distm o/s</i>	1	\$ 165.62	\$165.62	✓
REAR SHOCK ABSORBER MOUNTING <i>HH</i>	1	\$ 175.42	\$175.42	X
REAR LOWER ARM <i>distm o/s 497.50</i>	1	\$ 696.50	\$696.50	✓
REAR UPPER ARM <i>distm o/s 356.80</i>	1	\$ 499.52	\$499.52	✓
REAR KNUCKLE ARM <i>distm o/s 810.60</i>	1	\$ 1,134.84	\$1,134.84	✓
REAR STABILIZER BAR <i>HH</i>	1	\$ 436.10	\$436.10	X
REAR STABILIZER LINK <i>HH</i>	1	\$ 212.24	\$212.24	X
REAR TRAILING ARM <i>distm o/s</i>	1	\$ 439.88	\$439.88	✓
REAR ASSIST ARM <i>distm o/s</i>	1	\$ 479.08	\$479.08	✓
SUB TOTAL			\$26,315.27	10,719.63
LESS 20% <i>25%</i>			\$5,263.05	8,039.72
DISCOUNTED TOTAL			\$21,052.21	
REAR DOOR COMFORT & APPS STICKER <i>HC</i> SN	1	\$ 112.00	\$112.00	✓
REAR DOOR ADVERTISEMENT LOGO <i>HC</i> SN	1	\$ 140.00	\$140.00	✓
SUB TOTAL			\$252.00	497.00 637.00
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
Labour Charge				
Panel Beating	1	\$ 2,000.00	\$2,000.00	700/-
Spray Painting Charge	1	\$ 1,800.00	\$1,800.00	700/-
Wiring Charge	1	\$ 100.00	\$100.00	HH
Tuff Kote	1	\$ 100.00	\$100.00	40/-
Towing Charge	1	\$ 80.00	\$80.00	HH
Remove/Refix Cushion & Upholstery Rear	1	\$ 150.00	\$150.00	80/-
Remove/Refix Undercarriage (RR)	1	\$ 400.00	\$400.00	150/-
Transfer of Door Mechanism FRONT	1	\$ 80.00	\$80.00	60/-
Re-set Frt Power Window System	1	\$ 200.00	\$200.00	HH
Transfer of Door Mechanism REAR	1	\$ 80.00	\$80.00	60/-
Re-set Rear Power Window System	1	\$ 200.00	\$200.00	HH
Four Wheel Alignment	1	\$ 120.00	\$120.00	60/-
Diagnostic & Resetting To Erase Fault Code	1	\$ 550.00	\$550.00	7H
TOTAL LABOUR			\$5,860.00	1850.00
ESTIMATE TOTAL			\$27,164.21	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be				

21/11/2022 17:00

NA Auto

PI Part 9 days

(Signature)

LKK Auto

check part prices

Part after

with damaged parts

7/12 10,526.72