



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI22011698/Rny3q2 Date: 16/12/2022  Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	XE 4777E	Veh. Inspected	SLU 362C
Policy No.		Coverage (\$)	0.00
Claim No.	D22003636MFVS	Excess (\$)	0.00
Assign From	JOANNE TAN JO ANN	Assign Date	17/11/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA PRIUS HYBRID 1.8	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU003576006	Colour	GREY
Odometer	435760 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	DUNLOP	6 mm
L/H Front Tyre	195/65 R15	DUNLOP	6 mm
R/H Rear Tyre	195/65 R15	DUNLOP	6 mm
L/H Rear Tyre	195/65 R15	DUNLOP	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	17/11/2022	Inspection Date	18/11/2022
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		
<b>5a. Remarks</b>			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	